
SURVEY OF TWO (2) ONE (1) ACRE PARCELS OF LAND SITUATED IN THE WEST RLY PORTION OF THE NORTH HALF OF LOT NO. 1 PERRY'S SUBDIVISION JACKSON COUNTY, OREGON.



October 6, 1945

9.45

Scale: 1" =100'


Survey Narrative
Robert Castonguay, Jr.
Tad S. Blanton
O. D. Day
Otwell McLish, Jr.
September 20, 1983
Page Two

Parcel No. 2 of the Clabby survey, which was partitioned out of the overall Curtright property (Vol. 258, Page 28 D.P.) and conveyed to Arch Z. Stout et ux by warranty deed, Vol. 262, Page 627, D.R. The tracts being monumented now have been created by further partitioning of said Parcel No. 2.

Basis of bearings is Filed Survey No. 9717.
September 20, 1983

PROFESSIONAL
LAND SURVEYOR

JULY 16. 1967
GARY D. KAISER
N. BC 7



SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

SURVEY FOR: Robert Castonguay, Jr. 135 Arnold Lane

Medford, Oregon

O. D. Day 105 Arnold Lane Medford, Oregon

Tad S. Blanton 129 Arnold Lane Medford, Oregon

Otwell McLish, Jr. 85 Arnold Lane Medford, Oregon

SURVEY BY: Boyden Surveyors

108 Mistletoe Street

Medford, Oregon

PURPOSE:

A. To monument a boundary proposed to be established by a recorded boundary line agreement between the property of Tad S. Blanton et ux (Inst. No. 83-10651 O.R.) to the South and O. D. Day et ux (Vol. 322, Page 230 D.R.) and Otwell McLish, Jr. et ux (Inst. No. 67-08218 O.R.) to the North being located in Lot 1 of PERRY SUBDIVISION, D.L.C. No. 74 and the SW 1/4 of Section 27, T37SR2W, W.M.

To monument that tract described in Vol. 322, Page 230 D.R. (those boundaries not affected by the proposed boundary line agreement) and that 100+-foot wide portion of the tract described in Inst. No. 67-08218 O.R. fronting on Arnold Lane.

PROCEDURE: Control for the location of Lot 1 of PERRY SUBDIVISION and Arnold Lane was taken from Filed Survey No. 9717.

The proposed boundary line agreement was located per the client's request.

The North, South and East boundaries of those tracts desired to be monumented ('B' in the above "purpose") were determined from found monuments set by Surveyor "Clabby" in 1945 (see Exhibit 'A' to this narrative) on a survey for Curtright (assumed to be Amos F. Curtright). The boundaries of Lot 1 of PERRY SUBDIVISION as located on the Clabby survey are in error due to the fact he used the iron bolt monumenting the NW corner of D.L.C. No. 74 (see Deputy County Surveyor C. Z. Boyden's 1943 re-estab) as the NW corner of said subdivision. The true NV and SW corners of PERRY SUBDIVISION, as available now, were not yet recovered at that time. The tracts desired to be monumented on this survey are controlled by the boundaries of

