



**BOUNDARY LOCATION
PROPERTY SITUATE IN
NE 1/4 SEC 14 T 37S R 2W WM
JACKSON COUNTY OREGON**

J H CLABBY CIVIL ENGINEER
MEDFORD OREGON 15 NOVEMBER 1950
SCALE - 1" = 50'

Survey Narrative to Comply with Sec. 87-330, 1947 Oregon State Laws.

Survey for: R. I. Hague

Location: Northeast Quarter Section 14, Township 37 South, Range 2 West, Willamette Meridian, Jackson County, Oregon

Purpose of survey:

To cut up parcel into lots.

Procedure:

Found iron pipe at southeast corner of Block 6 of Valley Center Subdivision, and iron pipe at northeast corner and northwest corner of property shown on attached plat, all of which has been set by this office on previous surveys. Set additional pins as shown on plat.

J. H. Clabby

November 1950

