



Record Bearings used

Mon. (found)
E11 Cor. D.L.C. 42
T. 37S. R. 1W.

Mon. (found)
E.N.E. Cor. D.L.C. 42

BOUNDARY LOCATION
PROPERTY SITUATE IN
SW 1/4 SEC. 19, T. 37S, R. 1W, WM.
JACKSON COUNTY, OREGON
LELAND P. LOVEJOY - LAND SURVEYOR
MEDFORD, ORE. OCT. 19, 1951
SCALE 1"=50'

Survey Narrative to Comply with Section 87-3301947 Oregon State Laws

Survey for: Lilenquist Motors
Medford, Oregon

Purpose of Survey: To run out property boundaries

Survey Location: Southwest One-Quarter (1/4) of Section 19,
Township 37 South, Range 1 West, Willamette
Meridian, Jackson County, Oregon.

Survey procedure: Ran closed traverse from corner monument to corner
monument D.L.C. 42, Township 37 South, Range 1 West,
Willamette Meridian, including property shown on
map; tied in existing monuments and set 1" iron pipes
as shown on map.

Leland P. Lovejoy, Registered Land Surveyor

Work completed February 2, 1952

