


**BOUNDARY LOCATION
PROPERTY SITUATE in
Sec. 24, Twp. 37S., R. 2 West, W.M.
JACKSON COUNTY, OREGON.**

**J.H. CLABBY CIVIL ENGINEER
MEDFORD, OREGON**

MAY, 1953 SCALE: 1" = 60'



Survey Narrative to Comply with Section 87-330, 1947 Oregon State Laws.

Survey for: Al Bendickson

Location: Section 24, Township 37 South, Range 2 West Willamette Meridian,
Jackson County, Oregon.

Purpose of Survey:

To locate and describe a triangular parcel of land occupied by Mr. Bendickson's home and a store building now (May 1953) under construction.

Procedure: Found property corner monuments on northwesterly right of way line of McAndrews Road which included the initial point, a 1" iron pipe established on a previous survey, said pipe bears North 392.10 feet and East 2126.44 feet from the Southwest corner of D.L.C.No. 88, said township and range, from said point ran North 1° 00' West 356.69 feet, South 49° 14' East 242.16 feet, South 41° 45' West 266.08 feet to the point of beginning.

J. H. Clabby

May 1953

