

SURVEY NO.

SURVEY NARRATIVE TO COMPLY WITH ORS 290.250

SURVEY FOR:

K.O.G.A.P. MFG. INC.

P.O. BOX 1608 MEDFORD, OR 97501

AND

BOISE CASCADE CORP.

P.O. BOX 100 MEDFORD, OR 97501

LOCATION:

EAST 1/2 OF SECTION 20, T.38 S.,

R.2 W., W.M., JACKSON COUNTY, OREGON,

PURPOSE:

TO SURVEY AND MARK BOUNDARY LINES AND

ESTABLISH CORNERS AS SHOWN ON THE

ANNEXED MAP.

PROCEDURE:

SURVEY NO. 5608 BY THIS OFFICE IN WHICH WE TIED ALL OF THE EXSITING CORNERS OF SECTION 20 AND ESTABLISHED THE NORTH 1/4 CORNER WAS USED FOR CONTROL OF THIS SURVEY. TRAVERSES WERE RUN FROM THE SOUTH ONE QUARTER CORNER TO SOUTH EAST CORNER AND FROM THE SOUTH ONE QUARTER CORNER TO THE NORTH ONE QUARTER CORNER. THESE TRAVERSES CLOSED WELL ABOVE THE REQUIRED ACCURACY FOR THIS SURVEY.

RANDOM TRAVERSES WERE RUN ALONG LINES TO BE MARKED AND OFFSETS CALCULATED TO TRUE LINE WHICH WAS THEN BLAZED, PAINTED AND MARKED WITH METAL TAGS STAMPED BCC OR KOGAP AS APPROPRIATE.

A TOPCON GTS2 TOTAL STATION WAS USED IN EXECUTING THIS SURVEY.

THE FOLLOWING LISTED CORNERS WERE RECOVERED OR ESTABLISHED.

1/4 CORNER SEC 17/20. FOUND 2 1/2" GALVINIZED IRON PIPE SET FLUSH FROM WHICH BEARS:

A 18" DIA. PINE N 47°08' W 51.3 FEET SHOWS SCARS.

A 6" DIA. WHITE OAK S 84°39' E 38.2 FEET SHOWS SCARS.

C-N 1/16 CORNER SET 5/8 INCH IRON PIN FROM WHICH BEARS:

A 21" DIA. MADRONE S 63° E 11.0 FEET SCRIBED CN 1/16 S20 BT.

A 15" DIA. FIR N 76° E 34.2 FEET SCRIBED CN 1/16 \$20 BT.

3. N.E. 1/16 CORNER SET 5/8 INCH IRON PIN FROM WHICH BEARS:

A 13" DIA. CEDAR N58°W 36.1 FEET SCRIBED N.E. 1/16 S20 BT.

A 16" DIA. FIR N 43° E 14.1 FEET. SCRIBED N.E. 1/16 S20 BT.

4. C.E. 1/16 CORNER. SET 5/8 INCH IRON PIN FROM WHICH BEARS:

A 7" DIA. FIR N14°E 17.2 FEET SCRIBED CE 1/16 S20 BT.

A 12" DIA. MADRONE \$46°E 24.9 FEET SCRIBED CE 1/16 \$20 BT.

- 5. C. 1/4 CORNER. SET 5/8 INCH IRON PIN FROM WHICH BEARS:
 A 16" DIA. FIR S12°W 1.9 FEET SCRIBED C 1/4 S20 BT.
 A 10" DIA. FIR N65°W 32.1 FEET SCRIBED C 1/4 S20 BT.
- 6. C.S. 1/16 CORNER. SET 5/8 INCH IRON PIN IN ROCK MOUND FROM WHICH BEARS:

 A 17" DIA. FIR N40°W 26.2 FEET SCRIBED CS 1/16 S20 BT.

A 8" DIA. OAK \$63°W 29.8 FEET SCRIBED CS 1/16 \$20 BT.

A 18" DIA. FIR N37°E 31.0 FEET SCRIBED SE 1/16 S20 BT.

- 7. S.E. 1/16 CORNER. SET 5/8 INCH IRON PIN FROM WHICH BEARS:
 A 9" DIA. FIR N51°W 10.0 FEET SCRIBED SE 1/16 S20 BT.
- 8. 1/4 CORNER SECTIONS 20/29. FOUND A I INCH DIA. GALV. IRON PIPE WITH 2 INCH DIA. METAL FILLED EXPANDER STAMPED 1/4 20/29 1967 FROM WHICH BEARS:

A 8" DIA. OAK S48 1/2°W 118.2 FEET SHOWS SCARS.

A 24" DIA. OAK S $68\ 1/2^{\circ}W\ 110.9$ FEET ROTTED INTERIOR O.B.T.

A 12" DIA. OAK N51 1/2° W 17.7 FEET SHOWS SCARS.

A 48" DIA. FIR N9°E 108.7 FEET SCRIBE VISABLE O.B.T.

9. E. 1/16 CORNER 20/29 SET 5/8 INCH IRON PIN FROM WHICH BEARS:

A 6" DIA. FIR N46°W 12.3 FEET SCRIBED E 1/16 S20 BT.

A 12" DIA. FIR S23°E 23.9 FEET SCRIBED E. 1/16 S29 BT.

10. SECTION CORNER 20,21,28 AND 29 FOUND 1" GALVINIZED IRON PIPE WITH 2 1/2 INCH DIA. BRASS DISK C.S. 1970 FROM WHICH BEARS:

A 14" DIA. FIR N40°E 41.3 FEET SHOWS SCARS.

A 48" DIA. FIR STUMP S25°E 6.6 FEET SCRIBE VISABLE. 0.B.T.

A 22" DIA. FIR S72°W 46.9 FEET SCRIBE VISABLE. O.B.T.

A 30" DIA. FIR N19°W 57.4 FEET SHOWS SCAR.

DATE: APRIL 17, 1985

LARRY J. FRIAR
FRIAR-MOFFIT & ASSOC.
717 W. 10TH ST.
MEDFORD, OR 97501

* * RECEIVED * *

Date 4/24/85 BySL

This survey Consists of:

____ sheet(s) Map

_____ sneet(s) map _____ page(s) Narrative

JACKSON COUNTY
SURVEYOR

REGISTERED PROFESSIONAL LAMP SURVEYOR

JULY 16. 1971 LARRY J. FRIAR 961