



10321

SURVEY FOR BILL PARKS
S.E. 1/4 Sec. 25, T.36 S., R.2 W., W.M.
JACKSON COUNTY, OREGON
JUNE 17, 1985



LEGEND

- Monument found
- 5/8"x24" I. Pin with plastic cap stamped L.S. 505 SET
- x-x- existing fence



S.W. 1/16 COR.
3/4" I. Pipe

GIBBON

N89°47'15"W Per Survey No. 1525

528.00

ROAD

C.S. 1/16 COR.
B. CAP

SEE SURVEY NO. 353

**** RECEIVED ****
Date 7/19/85 By XL
This survey consists of:
1 sheet(s) Map
1 page(s) Narrative
JACKSON COUNTY
SURVEYOR

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Verlyn Thomas
OREGON
MAY 13, 1960
VERLYN D. THOMAS
505

SURVEY BY VERLYN THOMAS, PROFESSIONAL LAND SURVEYOR, MEDFORD, OREGON

25 1/4 COR.
B. CAP
36

10321

SURVEY NO. 10321

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

FOR: Bill Parks
110 Gibbon Road
Central Point, Oregon 97502

PURPOSE: To establish location of West property line as
described in legal description furnished by client.

PROCEDURE: Recovered brass cap monument at the C. S. 1/16
Corner of Section 25, and turned interior angle
from South Quarter corner to a 3/4" pipe established
as the S. W. 1/16 corner, thereby establishing center-
line of Gibbon Road. Established West line of subject
property parallel with the North-South center line of
Section 25.

It should be noted that title lines donot conform to
existing fences.

36-2W-25C T. L. 2000

