

Survey No. 10393

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 REVISED OREGON STATUTES

SURVEY FOR:

Honorable Board of Commissioners

of Jackson County

SURVEY BY:

Edward A. McGinty Jackson County Surveyor County Courthouse Medford, Oregon 97501

LOCATION:

Donation Land Claim 50, located in the Northwest quarter of Section 12, Township 38 South, Range 2 West, of the Willamette Meridian in Jackson County, Oregon.

BASIS OF BEARING: South line of Survey No. 3712.

PURPOSE OF SURVEY: At the request of the Jackson County Board of Commissioners "to establish the government corner(s)" that would allow local land owner(s) to engage a surveyor to resolve property line altercations.

After considerable research of deed records, surveys of record, previous testimony, and inquiries to the previous county surveyor, a traverse was made along the south line of said donation land claim, which it was determined that the Southeast corner of Donation Land Claim No. 50 was not lost but It is clearly evident that the location of the Southeast corner was well known on May 8, 1897 and for some years later.

On that tract of land described in Volume 32, page 472 in the establishment of the southwest corner, the calls for the point of beginning(2) being 8.55 chains west of the Southeast corner of Donation Land Claim 50. This point (2) was perpetuated over the years and in 1951 identified to Clabby, a local engineer, while he was in the process of surveying. (See survey No. 378. Also note that he does not indicate a monument on his map but does show this monument on his In 1968, this same point (2) was identified to me as I was making a partial retracement of Clabby's survey (see my survey no. 3712). Note point (2) is shown in my personal field notes. During the process of this survey in order for a partial verification of the monument set by Clabby, I made a tie to the South-Southwest corner of Donation Land Claim 50.

With my previous knowledge and experience of the area and by using the best available and preponderous evidence, the Southeast corner of Donation Land Claim 50 was at a point on line extended at distance 8.55 chains easterly of point (2). This does concur closely to the original records (East 1320 feet) and as well the occupation of land adjoining northerly.

In the late 1960, Hugh Ingle unfortunately made a survey (not of record), using the monument found at point (2) which he identified as the Northwest corner of government lot, which may have lead to some of the confussion of some of the land owners to the south.

MONUMENTS:

- (1) Fd. 1 inch pipe, 12 inches high with a brass cap marked and described in the County Surveyor's official records.
- (2) Fd. a 1 inch iron pipe, 8 inches deep.

(3) Fd. a 1/2 inch iron pin in concrete, 16 inches deep.

(4) Set a 1 inch iron pipe, 36 inches long with brass cap mkd. SE DLC 50 T38S, R2W, approximately 12 inches deep. REGISTERED See official records. **PROFESSIONAL**

DATE: November 8, 1985

OREGON EDWARD A. McGINTY

LAND SURVEYOR

Sec. 12, T38SR2W