

## SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 ORECON REVISED STATUTES

SURVEYED FOR:

Honorable Board of Commissioners

of Jackson County

SURVEYED BY:

Edward A. McGinty

Jackson County Surveyor County Courthouse Medford, Oregon 97501

LOCATION:

East quarter corner of Section 12, Township 38 South, Range 2 West, also being the West quarter corner of

Section 7, Township 38 South, Range 1 West.

PURPOSE OF SURVEY: This survey was made in conjunction with Survey No. 10393,

as requested by the Board of Commissioners.

## PROCEDURE:

The original monument for the quarter corner between Sections 7 and 12, calls for a post set in a cultivated field, in January 1854. Presently and for many years this position has been in an orchard. After diligent search in county records and in the field for a monument, this corner position was considered lost. The procedure for re-establishment of this corner was the standard procedure of single proportional measurement from the nearest corner North and the nearest corner southerly.

At the quarter corner between Sections 7 and 12, set an iron pipe, 1 inch in diameter, 36 inches long, 6 inches in the ground with a brass cap  $2\frac{1}{2}$  inch in diam. marked  $\frac{1}{4}$  12/7 CS 1985. For new references see County Surveyor's official records.

At the section corner to Sections 1, 6, 7 and 12 and the section corner to Sections 7, 12, 13 and 18, found monuments set in previous county surveyor records. For additional information see official records of the County Surveyor.

\* RECEIVED \* \*

Date 11/14/85 By St

This survey Consists of: \_\_ sheet(s) Map

> JACKSON COUNTY SURVEYOR

page(s) Narrative

DATE: November 13, 1985

REGISTERED PROFESSIO**NAL** LAND SURVEYOR

> JULY 10, 1953 EDWARD A. McGINTY