

## SURVEY NARRATIVE as per PARAGRAPH 209.250 OREGON REVISED STATUTES

Survey for: Harold Hardesty

1291 Oak Street

Ashland, Oregon 97520

Location: S.W. 1/4 of Section 23 Township 39 South, Range 1

East, Willamette Meridian, Jackson County, Oregon.

Purpose: To replace the SE-SW 1/64 corner of Section 23 which

was inadvertently destroyed by an adjacent granite

mining operation.

Procedure: Found the controlling corners to the west and south

as per RS No. 9060, which included the following: C-S-SW 1/64 corner of Section 23; and a 5/8 inch iron pin located on the west right of way of Tolman Creek Road, on tangent with the E-W 1/64 of Section 23 and the missing corner. These found monuments were used to determine the position of the lost monument. The replacement monument was set in place with a theodolite and E.D.M. Three reference objects were also tied to the replacement monument during this survey.

Basis of

Bearing: NOAA True Bearing as per R.S. # 9060.

November 20, 1985

Roger Kauble, RPLS #1822 P. O. Box 1252 611 Siskiyou Blvd. Ashland, Oregon 97520

REGISTERED
PROFESSIONAL
LAND SURVEYOR
OREGON
OULY 13,1979
ROGER D. KAUBLE
1 8 2 2

\* \* RECEIVED \* \*

Date 12/4/B5 By \*

This survey Consists of:

\_\_\_\_\_\_ sheet(s) Map

\_\_\_\_\_ page(s) Narrative

JACKSON COUNTY

SURVEYOR