

December 19, 1985

£ .)

CO

Medford, Oregon

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED CHAPTER

SURVEY FOR:

Jackson County

SURVEY BY:

Edward A. McGintv

County Surveyor

LOCATION:

Re-established corners for Donation Land Claims 68, 69 and 70, Township 37 South, Range 2 West, Willamette Meridian,

Jackson County, Oregon.

DATE:

December 19, 1985

BASIS OF BEARING: Survey No. 3311, N89°52'40"E, South line DLC 69.

PURPOSE:

The restoration of Donation Land Claim corners; Southwest corner of 69, East Northeast corner of 68 and the Northwest

corner of 70.

PROCEDURE:

All donation land claim corner monuments recovered were flush with surface with the exception of the Southwest corner of No. 69, which was approximately 5 ins. tilted northwesterly. This monument was reset and brass capped to it's previous position.

The 5/8 ins. iron pin 6 ins. deep shown on the west line of DLC 69 and the centerline of Ross Lane extended was set by me approximately 20 years ago as a reference point.

This map was made in conjunction with corner restoration which is intended as part of this narrative.

* * RECEIVED * *

Date 12/31/85 By Sc

This survey Consists of:

/_ sheet(s) Map

_ page(s) Narrative JACKSON COUNTY

SURVEYOR

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

JULY 10, 1953 EDWARD A. McGINTY