

Mon. (Found)
E.L. Cor. D.L.C. 42

Mon. (Found)
NE. Cor. D.L.C. 42

N. 89° 56' 40" E. 3511.15'
933.20'

853.00'

1071

BEAR CREEK

CREEK

ROAD

BIDDLE ROAD

N. 7° 41' 20" W. 706.05'

N. 89° 52' 40" E. 296.53'
R = 2894.79'
L = 5.48'
LC N 7° 44' 35" W 5.47'

N. 0° 09' 20" W. 505.91'
(Rec. 505.90)



PROPERTY SURVEY FOR
BUTTRESS & McCLELLAN, INC.
LOCATED IN D.L.C. No. 42, T.57S, R.1W, N.M.
L.P. LOVEJOY L.S. MEDFORD, ORE.
SCALE: - 1" = 200' DEC. 28, 1957
JACKSON COUNTY OREGON

• DENOTES 1" G.I. PIPE SET IN CONCRETE

REGISTERED
OREGON
LAND SURVEYOR

Leland P. Lovejoy

NOVEMBER 16, 1948
LELAND P. LOVEJOY
282

S. 0° 04' 30" W. 1068.66'

498.28'
S. 89° 59' 20" W.

N. 89° 59' 20" E. 853.00'

1/4 JACKSON STREET
S. 89° 39' 20" W. 634.19'

S. 0° 04' 30" W. 1068.66'

EAST JACKSON STREET

BEARINGS BASED ON SOLAR OBSERVATIONS

Mon. (Found)
SE. Cor. D.L.C. 42

N. 0° 04' 30" E. 1068.66'

Survey Narrative to Comply With
Section 87-330 of 1947 Oregon State Laws

Survey for: Buttress & McClellan, Inc.
1900 Beverly Boulevard
Los Angeles, California

Purpose of Survey: Run out property boundaries.

Survey Location: D. L. C. 42, Township 37 South,
Range 1 West, Willamette Meridian,
Jackson County, Oregon.

Survey Procedure: Found corners as shown on map.
Set 1" galvanized iron pipe in concrete
as indicated on map.

Leland P. Lovejoy
Registered Land Surveyor
Work completed December 15, 1957

