



36 3w 1

Survey No. 11017

Survey Narrative To Comply With O.R.S. 209.250

Survey For: John Walsh
9451 John Day Drive
Gold Hill, Oregon 97525

Location: Sec. 1, T. 36 S., R. 3 W., W.M., Jackson
County, Oregon.

Purpose: To locate and monument the corners of Tax
Lots 502, 504, 505, and 506 as requested by
the client as part of a pending sale of the
above Tax Lots.

Procedure: Corner ties were made to the controlling
corners of section 1. The N 1/4 corner as set
in the original survey was searched for but
not found due to the cultivation of the land.
The original bearing trees also were not
located during my search. I set the 1/4
corner in proportion to the original record
distance. This position fit the call to the
creek to the west. The position of the SW cor-
ner of the section was determined by propor-
tionate calculation using the W 1/4 corner
and the Meander Corner on the South line
of the section. I then subdivided the
section and using found monuments set by
Survey Nos. 4835, 4836, 10024 and pins set
by the OSHD on the Easterly R/W of Highway
234, I determined the position of the Lot
corners and set pins as shown on the attached
map.

Date: September 25, 1987

36S R3W S1 TL 502, 504, 505, 506

Larry J. Friar
L.J. Friar & Assoc.
717 West 10th
Medford, OR 97501

