


PLAT
 SHOWING A SURVEY IN SECTION
 30, T.34 S., R.3 W., W.M., JACKSON
 COUNTY, OREGON.



LEGEND

- SET 5/8" X 30" IRON ROD WITH PLATIC CAP MARKED "NYGREN LS 1035":
- FOUND 5/8" IRON ROD.
- ⊙ FOUND BRASS CAP.
- MARKED LINE WITH RIBBON, RED PAINT AND ALUMINUM POSTS.
- MERIDIAN IS BASED ON THE SOUTH LINE OF SECTION 30 PER RECORDED B.L.M. SURVEY NO. 7.
- SURVEY NARRATIVE IS SEPARATE DOCUMENT.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR
 OREGON
 GERALD V. NYGREN
 AUGUST 22, 1975
 1085

** RECEIVED **
 Date 11/19/87 By *[Signature]*
 This survey consists of
 1 sheet(s) Map
 1 page(s) Narrative
 JACKSON COUNTY
 SURVEYOR

SURVEYED FOR: TIMBER PRODUCTS CO. 25 E. McANDREWS ROAD MEDFORD, OREGON 97501	GERALD V. NYGREN 522 BARKER DRIVE MERLIN, OREGON 97532	DATE: OCT. 27, 1987. SCALE: 1" = 400' JOB NO. 87-30
---	---	---

11038

SURVEY NARRATIVE

DATE: October 27, 1987.

SURVEYED FOR: Timber Products Company
25 E. McAndrews Road
Medford, Oregon 97501

SURVEYED BY: Gerald V. Nygren
522 Barker Drive
Merlin, Oregon 97532

LOCATION: Section 30, Township 34 South, Range 3 West,
Willamette Meridian, Jackson County, Oregon.

PURPOSE: Mark the boundary lines of the West Half of said
Section 30.

PROCEDURE: For control I surveyed to monuments found as shown
on Plat. The South Quarter corner of said Section
30 was set by B.L.M. in A dependent survey (see B.L.M.
survey No. 7) and was found to be out of position
by Oregon State standards. I re-establish the South
Quarter of said Section 30 as shown on Plat.

Meridian is based on the South line of said Section 30
per recorded B.L.M. survey No. 7.

A Wild T-16 theodolite and MAC-1E EDM were used to
execute this survey.

