

Paul Rynning  
County Surveyor  
Medford, Oregon

SUBJECT: Re-establishment of 1/4 corner.

Township 36 South, Range 1 West, W.M.



The 1/4 corner between Section 27 and 28, found no evidence of original mound, set a 1 1/4 inch pipe, 28 ins. long, 6 ins. below the surface at a proportional distance from south to north from which

1/4 x 20 ins. pipe bears east 15 feet.

1/4 x 24 ins. pipe bears west 30 feet.

Fence corner bears S.70°W., 36 feet.

Power pole, No. B4501, bears N.23 1/2°W., 79.5 feet.



*Edward A. McGinty*

