

11265

SURVEY FOR VICTOR STAFF

LOCATED IN LOT 10, AMENDED PLAT OF
RIVERSIDE SUBDIVISION, JACKSON COUNTY, OREGON
S.E. 1/4 SECTION 24, T. 36 S., R. 4 W., W.M.

February, 1988



**** RECEIVED ****
 Date 3-9-88 By SK
 This survey consists of
1 sheet(s) Map
1 page(s) Narrative
 JACKSON COUNTY
 SURVEYOR

Scale: 1" = 100'

LEGEND

- Monument Found
- Set 5/8"x24" Iron Pin with plastic cap stamped L.S. 505

AMENDED PLAT OF
RIVERSIDE SUBDIVISION

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Verlyn Thomas
 OREGON
 MAY 12, 1900
 VERLYN D. THOMAS
 L.S.

LOT 10

LOT 6

(PLAT REC. N89°36'W 1377.5) 1377.54

1" I. Pipe

WITNESS
CORNER

355.00

5/8" I. Pin

SEE SURVEY
NO. 8714

LOT 11

36-4W-24D T.L. 2700

Survey by Verlyn Thomas, Professional Land Surveyor, Medford, Oregon.

11265

7

SURVEY NO. 11265

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

FOR: Victor Staff
2055 Rogue River Highway
Gold Hill, Oregon

LOCATION: Lot 10, AMENDED PLAT OF RIVERSIDE SUBDIVISION
S. E. 1/4 Sec. 24, T. 36 S., R. 4 W., W. M.
Jackson County, Oregon.

DATE: February 1988.

PURPOSE: To determine south line of client's property.

PROCEDURE: Traversed from 5/8" iron pin established by Survey No. 8714
as the Southeast corner of Lot 10, westerly to a 1" iron
pipe located at the Southwest corner of Lot 10.
Set 5/8" iron pin witness corner 9.5 feet easterly of I-5
right-of-way fence.

SURVEYOR: Verlyn Thomas
304 South Holly
Medford, Oregon

