SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

Rogue River National Forest

P. 0. Box 520 Medford, OR 97501

LOCATION:

Section 5, Township 36 South, Range 4 East,

Willamette Meridian, Jackson County, Oregon.

PURPOSE:

To preserve and protect deteriorating corner

evidence.

PROCEDURE:

Utilizing existing corner evidence recovered at the corner point, I verified the corner point from recovered accessories, stabilized the monument as needed and marked additional accessories as required to perpetuate the corner point.

BASIS OF BEARING:

G.L.O. record - 1925.

DATE:

September 26, 1988

HAROLD L. CENTER
Registered Professional Land Surveyor
Oregon Certificate No. 1071

PROFESSIONAL
LAND SURVEYOR

OF EGON
MARCID L CENTER
ANY 28 1976
No. 1071

* * RECEIVED * *

Date 10 /21/88 By SK

This survey Consists of:

sheet(s) Map

pege(s) Narrative

IACKSON COUNTY
SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The 8th Standard Parallel South, Township 35 South, Range 4 East, Willamette Meridian, Jackson County, Oregon, was surveyed by Rufus Moore under Contract No. 504, dated May 27, 1884. Surveyor Moore established the one-quarter corner for Section 5, Township 36 South, Range 4 East, and Section 32, Township 35 South, Range 4 East, during this survey.

DIAGRAM	
T35S R4E SC	
1/4 S32	
T36S R4E	
1988	
LS 1071	

Lincoln Wilkes recovered this standard corner monument and changed it to one of minimum control for Section 32 only under Special Instructions for Group No. 86, dated July 11, 1922.

Description of corner evidence found:

At the corner point, I found a 9"x6"x5" stone, marked SC1/4 on north side, and the following accessories:

A 39-inch diameter pine bears N.04°01'W., 98.15 feet distance, with a healed blaze.

A 13-inch diameter pine bears $N.06^{\circ}06^{\circ}E.$, 21.15 feet distance, with scribing SC1/4 visible in an opened blaze.

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner point, I set a 21/2-inch diameter iron post 31 inches in the ground with a 21/2-inch diameter brass cap monument, marked as shown in the diagram, and mark the following accessory:

A 13-inch diameter pine bears N.64°19'E., 35.30 feet distance, scribed 1/4 S32 LS1071 BT.

September 26, 1988

HAROLD L. CENTER Registered Professional Land Surveyor Oregon Certificate No. 1971



Office of	County of
State of , I hereby co	ortify that the within instrument was filed in this office
	by
(COUNTY OFFICIAL)	(DEPUTY)