



- Indicates line run on this survey
 - Indicates 5/8" x 30" Rebar with yellow plastic cap marked TEMPLIN RLS 2359 Set.
 - Indicates 5/8" Iron Rod with BURNELL cap per R.S. No. 5910 Found.
- Bearings based upon R.S. No. 5910

RECEIVED
 Date 4/17/89 by SK
 This survey is correct as shown on this plat.
 Jackson County Surveyor

RICHARD TEMPLIN LAND SURVEYING
 2042 BARBER PL. 776-0801 MEDFORD, OREGON

DEPENDENT RESURVEY

LOCATED IN
 NW 1/4 of SECTION 30, T. 36S., R. 2W., W.M., JACKSON COUNTY, OR.

PREPARED FOR: Richard Van Der Puff
 Central Point, Oregon

DATE: April 15, 1989
 SCALE: 1" = 60'

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

R.T. Templin

RICHARD TEMPLIN

RICHARD G. TEMPLIN
PROFESSIONAL LAND SURVEYOR

2042 Sandra Pl.
Medford, Oregon 97504
(503) 776-0991

SURVEY NO. 11565

SURVEY FOR: Mr. Richard Van Der Puil
9191 Blackwell Rd.
Central Point, Oregon

Location: Located in the Northwest Quarter of Section
30, Township 36 South, Range 2 West,
Willamette Meridian, Jackson County, Oregon.

Purpose: To monument those particular corners as shown
on accompanied plat per O.R. 88-19605.

Date: April 17, 1989

Basis of
Bearing: Bearings were based upon Recorded Survey
number 5910.

Procedure: Utilizing a Wild T-16 and Mac 1E EDM, tied
in the monuments set in R.S. No. 5910. The
witness corner monument at NW corner of O.R.
74-15275 was not found. Calculations of
monuments found per R.S.No. 5910 were within
acceptable tolerance. From said found
monuments, set corners as shown on accompanied
plat and ran lines between set corners for
fence line purposes.

