MINOR PARTITION MAP Located in the Northeast and Northwest quarters of Section 21, Township 36	
South, Range 3 West of the Willamette Meridian, Jackson County, Oregon File 88-28 MP	
for	
Surveyor's Certificate: I, Herbet A. Farber, a duly registered Land Surveyor of the State of Oregon, hereby certify that this map correctly represents a survey made by me or under my direction and complies with regulations for "Minor Land Partitions". JOHN A. JACKSCH	
REGISTERED PROFESSIONAL LAND SURVEYOR OREGON MERBERT A FARPER P.O. Box 5286 Central Point, Oregon 97502 NIVERSTATE Fd. NW corner of section 21 bears Notice 12 bears Notic	
Water Right Statemet Instrument no. 89-26127 Official Records. ROAD	
Approval: Approval by the Jackson County Department of Planning and Development E DITCH DATA 1 Sept 1 Sept 20 Sept	
Basis of bearing: Filed survey no. 10530 C V4 (see narrative) C V4 (see narrative)	
● Set 5/8"x24" iron pin w/ yellew plastic cap marked "FARBER LS 2189" ▲ Set witness corner 5/8"x 24" iron pin w/ yellow plastic cap marked "FARBER LS 2189"	
Scale: 1" = 200' ** Description **	
Date: June 16, 1989 Date 11-15-89 By5t This survey Consists of:	
I, Herbert A. Farber, hereby certify that this is an exact copy of the original. JACKSON COUNTY SURVEYOR	
Thursta, to	

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

Survey for:

John A. Jaksch

13418 Sand Rock Court

Chantilly, Virginia 22021

Location:

Located in the northeast and northwest quarters of Section 21, Township 36 South, Range 3 West of the Willamette Meridian,

Jackson County, Oregon.

Purpose:

To survey and monument the dividing line for a minor partition and boundary line agreement as per Jackson County Department of Planning and

Development File 88-28-MP.

Procedure:

Deed corners where tied to existing control north of the Rogue River. Many of the deed corners, called for in Instrument No. 87-26839 of the Official Records of Jackson County, Oregon, now reside in the middle of Interstate 5. I recovered right of way monuments for the interstate, which now includes Old Stage Road formerly a County Road, and held it as the north line of the surveyed property. The lines which where surveyed are marked as such on the accompanying map. All other lines are deed lines, of said instrument, for mapping purposes only. The line marked see narrative is the northerly right of way line of the Gold Hill Irrigation Ditch which was not surveyed.

The basis of bearing is the east line of filed survey no. 10530.

Surveyed by:

Farber Surveying P.O. Box 5286

June 16, 1989

Central Point, Oregon 97502

Date:

PROFESSIONAL LAND SURVEYOR

Houta, Zu

OREGON JULY 26, 1905 HERBERT A. FARBER 2009 * * RECEIVED * *

Date 11-15-89 By 5

This survey Consists of:

______ sheet(s) Map

_____ page(s) Narrative

JACKSON COUNTY
SURVEYOR