## PARTITION PLAT NO. P-47-1990

## MINOR LAND PARTITION

Located in Lot 20 of BOES SUBDIVISION, in the SE 1/4 Section 34 In D.L.C. No. 57, T. 36 S., R. 2 W., W.M.

City of Central Point, Jackson County Oregon (1) = R = 170.00°  $\Delta = 06^{\circ} 00^{\circ} 17^{\circ}$ L = 17.82" LC = 3 18° 56' IT E 17.81 (2) = R = 70.00° SCALE: 1" = 50'  $\Delta$  = 68° 00' 00" L = 83.08' LC = \$ 55° 56' 20" E 78.29' LOT 19 LOT N 89° 56' 20" W 215,30' N 89° 59' 47" W 22L96' (Rec. N 89° 56' 20" W 215.42') (Rec. N 89° 56' 20" W 222.00') PARCEL I 0.457 Ac. Re: Survey # #567 Re: Survey # #403 LOT 20 Re: Survey # 6069 PANONO PARCEL 2 0.568 Ac. 名り

SURVEYOR'S CERTIFICATE:

I, Roger R. Roberts, a duly Registered Surveyor of the State of Oregon, do hereby certify that this map correctly represents a survey made by me and complies with the regulations for Minor Land Partitions and the following is an accurate description of the tract of land set forth hereon:

Lot 20 of BOES SUBDIVISION in Jackson County, Oregon, according to the official plat thereof now on record.

Subscribed and sworn to before me this 500 day of Qual, 1990

APPROVALS:

Reviewed by City of Central Point for conformance with land use regulations for minor land use partition and granted minor land partition approval via City Council Resolution No. 544. County Surveyor approval required pursuant to ORS 92.100.

Reviewed and approved by Jackson County Surveyor

Filed in the Office of the Jackson County Surveyor as Survey No. 12013

STATEMENT OF WATER RIGHTS:

See Document No. 90-14890, Official Records of Jackson County

RECORDER'S CERTIFICATE:

Filed for record this 15 day of Quine, 1990, at 8:50'clock, Am., and recorded as PARTITION PLAT NO. P-47-1990 of "RECORD OF PARTITION PLATS" in Jackson County, Oregon.
INDEX VOLUME \_\_\_\_ PAGE 47

County Clerk

= Found D.L.C. Corner (J.C. Brass Disk)

(Rec. 2607.00')

(Rec. 133.49')

UPTON

(\$ 13° 48' 25' E 0.09"

O = Found 5/8" iron pin - Boes Subdivision

Found 3/4" iron pin-private survey

LANDMARK SURVEYING

205 West Ninth St.

Medford, Oregon

June 1, 1990

(90-007)

□ = Well (water)

S 89° 56' 20" E-

● = Set 5/8" X 24" iron pin with orange plastic cap marked "R Roberts LS 1656"

E Found 5/8" iron pin - private survey

SURVEY BY:

SURVEY FOR:

--- J56.06<sup>.</sup> - - -

-- - I270.8I' -- -

2621.85' - - - -

(Rec. 156.00')

E. C. Brittsan 5394 Teresa Way Central Point, Oregon

97502

Basis of Bearing 637 (Boes Subdivision)

-SSW DLC 57

-t . 5 LHEU PROFESSIONAL

SE DLC 57

I certify this to be an

exact copy of the original plat.

Date 6-15-91 By 35 This is then Gersysts of Mar. Destruction of JACKSON LOOMER

36 2W 34D T.L. 201

Badly bent westerly

12073

## SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

E. C. Brittsan 5394 Teresa Way

Central Point, Oregon

LOCATION:

Lot 20 of BOES SUBDIVISION Southeast quarter of Section 34

Donation Land Claim No. 57

Township 36 South, Range 2 West, WM.

Central Point, Oregon

**PURPOSE:** 

Minor Land Partition

PROCEDURE:

Original subdivision monuments were located as shown on the plat map, along with several monuments set on subsequent surveys. The south boundary of DLC 57 was located in order to determine the north right of way boundary of Upton Road. The monument at the southeast corner of Lot 20 was found to be in the right of way by 0.09 ft. Its location was held to determine the alignment of the east boundary of the lot.

The northwest corner of the lot was established at record location from the found monument at the southerly end of the right of way curve. The original monument set for the northerly end of the right of way curve has evidently been destroyed.

The right of way curve at the intersection of Upton Road and Raymond Way was determined by bearing-bearing intersection, using plat record bearings.

The monuments along the partition line were set according to the client's instructions.

Basis of bearing: Plat of BOES SUBDIVISION

June 11, 1990

\* \* RECEIVED \* \*

Date 6-15-90 By 5½

This survey Consists of:

\_\_\_\_\_\_ sheet(s) Map

\_\_\_\_\_ page(s) Narrative

JACKSON COUNTY
SURVEYOR

PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
ROGER R. ROBERTS
1656

Roger R. Roberts Landmark Surveying 205 West Ninth St. Medford, Oregon