
APPROVAL:	MINOR		ARTITION	RECOR	RDING
	PARTIT		No. P-33-1991	FILED FOR RECORD THIS THE 10 AT $9:05$ O'CLOCK A M. AND REC	
John 111 Cample 4-	9-9/ Donation Land	located in Claim No. 41 in	the Southwest Quarter	P-33-199/ of the RECORDS OF INDEX VOLUME 2 , PAGE	
ASHLAND PLANNING COMMISSION PA #91-025	Twp. 39 South, Rge.	. 1 East of the	er of Section 4, Willamette Base & Meridi	an,	2 ·
APPROVAL	—— Clly of	ASHLAND, JACKSU	N COUNTY, OREGON	County Clerk	Deputy
Examined and Approved this 9day of	April, 19.91 Bill J.			COUNTY SURVEYOR Fi	le No. <u>12467</u>
City Surveyor		680 Oak Str Ashland, Orego		WATER RIGHTS	CTATEMENT.
Found Iron Pipe with Brass Disk marked:— City of Ashland No. 127, in a Monu. Case. Re: Recorded Survey No. 9234	SURVEYOR'S CER		I hereby certify that this plat is a CAD	See Document No	•
	I, Everett L. Swain, Registered Surveyor of the State of Oregon No. • that this plat is conformable to the state of the st	759, hereby certify	generated duplicate of the original.	Official Records of Ja Oregon.	
* * RECEIVED * * Date 4-10-91 By	the survey has been correctly executed the survey has been correctly executed the State the following is an accurate description.	ited within the require of Oregon and the	Country V. Locality	or egon.	
This survey Consists of:	lines of the parent tract of land a	as set forth hereon:	-	e Willamette Base and Meridian. Ja	ckson County, Oregon:
The properties with the second	TUENOE OLIVE DO LEMES ET MINULES 40 LANGE	onds East along the South extension of the Easteriv	erly boundary line of sald Donation Lo right of way line of Oak Street; THEN	and Claim (deed record distance of NCE North 14 degrees 52 minutes 23	66.6 feet) for a distance seconds East (deed record
SURVEYOR	to a found 5/8 inch iron rod for the TRUE East) along said right of way line for a c a found 5/8 inch iron rod Witness Corner N	POINT OF BEGINNING; THEN distance of 68.20 feet to	ICE continuing North 14 degrees 52 mln: a point which bears South 89 degrees	utes 23 seconds East (deed record 59 minutes 37 seconds East for a	North 14 degrees 52 minutes distance of 1.00 foot from
NORTH /	feet) for a distance of 990.00 feet to a fo 5th day of July, 1990 as Partition Plat No West along the Southeasterly boundary ther	ound 5/8 inch iron rod si	tuated at the Northeast corner of Pareds of Partition Plats in Jackson Coun	cel No. I of that Minor Land Parti ty, Oregon; THENCE South 14 degree	tion filed for record the s 52 minutes 23 seconds
	degrees 52 minutes 23 seconds West for a constant of the said Parcel No. 1; THENCE North 73 degrees pipe; THENCE South 69 degrees 36 minutes 5	distance of 3.50 feet to s 15 minutes 04 seconds W	a point in the Northeasterly right of Vest along said right of way line for (way line of Clinton Street and that distance of 108.68 feet to a fou	e Southeasterly corner of nd 1/2 inch galvanized iron
75' 76' 78'	inch galvanized Iron pipe; THENCE continuing inch galvanized Iron pipe situated in the East for a distance of 72.01 feet to a found	ing along said right of w Westerly right of way li	ay line, North 89 degrees 59 minutes 3 ne of Carol Street; THENCE leaving sa	37 seconds West for a distance of id right of way line, North OO deg	20.12 feet to a found 1/2 rees 04 minutes 09 seconds
	found 5/8 inch iron rod; THENCE North 14 of minutes 37 seconds West for a distance of those apparent on the land.	degrees 52 minutes 23 sec 220.00 feet to the point	onds East for a distance of 68.20 fee	t to a found 5/8 Inch Iron rod; TH	ENCE North 89 degrees 59
, EV	NOTARY Subscribed and sworn to before me this	DENNIS P. ERNST	PRO	FESSIONAL	Englit & Solice
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		NOTARY PUBLIC - OREGON My Commission Expires 4/20/92	EMA	D SURVEYOR	SURVEYOR LS 759
Fd. Witness Corner is N.89° 59' 37" W., i.0' from true property corner location / 346.6	Reco (0'(R.S. No. 12139=346.65')		j	DREGON ULY 8, 1966 RETT L. SWAM	
DITCH DITCH	IRR 220.00' NO. 2 No. 2 N 14°52' 23" E	770.00'	GENERAL LOCATION roximate location — 19	SURVEYO	DR
÷/5\/		2.623 Acres +/- Wate	an existing Storm er drainage ditch. Swaln sknown Easement	·	PRIL 6, 1991
ος W 89° 59' 37' 220. 00'	N 14° 52' 23" E 68.20' Private	01	in the Ashlan	_	lephone: 482-4318
DEED R	Irrigation N 89°59'37"W 5 COURSE BEARI	NG DISTANCE	N (73. W.O. W.O. W.O. W.O. W.O. W.O. W.O. W.		UE MERIDIAN at the S Centerline Sec. 4
\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	L! S 00°00' L2 S 86°36' L3 S 69°36' L4 S 69°36'	21"E 18.78' 53"W 63.34' 53"W 57.54'	108. 68' 0 WI THE CA	•	derived from N.O.A.A. net) th redish plastic cap marked: 2"+/- per Recorded Survey lrrlg. Ditch. uth, 0.5' +/
23" E / 14.52	L5 N 89°59° L6 N 00°04' L7 S 51°46' L8 S 16°49'	21"W 65.27' 31"W 19.18'	CLINTON CLINTON	Fence c East-West brgs. So Found galv. iron pipe with shown hereon or unless as	outh, 0.5' +/ n brass disk or cap as otherwise shown.
0 4 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	L9 \$ 24°25' L10 \$ 17°06'	25"W 35.18" 43"W 20.95'		Found 5/8 inch iron rod wi	th cap marked: EL SWAIN RLS 759
EEO RE		Il Power Lines. is approximate.	BH SUNSHINE STON STREE	Found 1/2 inch galv. iron per Partition Plat No. P-9 Found 3/4 inch galv. iron per Partition Plat No. P-9	
of Donation Land Claim No. 41 Fd. Tack in conc			A A A BULL	Found 5/8 inch iron rod with Cor. RLS 759, per Red O Set 1/2 x 24 inch galvaniz	th red plastic cap marked: corded Survey No. 7441.
	Survey No. 10315 ENCUMBRANCE	Sewer Easement as set forth	in Volume 357, Page 485 of the poly, Oregon. Situated along the general area	<pre>plastic plug marked: SWAIN Wood fence c East-West+/-, Irrig, ditch brgs, South,</pre>	LS 759, exposed 1" brgs. South, 2.5'. Center 1'+/
66.52' (D.R. 66.6') S 89° 57' 42" E 2720.73'	the	Southerly boundary line of	Parcel No. 2, as shown above.		y, Oregon.
Southedst Corner 3. Telephone & Telegraph right of way as set forth in Volume 144, Page 159 of the Deed Records of Jackson County, Oregon. The exact location is not evident on the Parcels of land as set forth above.					
100 0 100 200 300	Claim No. 41. Chisel marks on manhole rim as 5.	There are several other docu	tc. as set forth in Volume 258, Page 406 of uments of record for electrical rights of w line which is now over and across the East	ay but none that can be directly	regon. Job: BR 4 9T File: BR 4 9T
GRAPHIC SCALE - 1" = 100' Tax Lot 1400, 39-1E-04CA & Tax Lot 402, 39-1E-04DB	Tied in 1972, 1977 & 1979				Sheet I of I



Survey No. 12467

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

BILL J. & GLORIA P. RICHKY

680 Oak Street

Ashland, Oregon 97520

LOCATION:

Situated in Donation Land Claim No. 41 in the Southwest

Quarter and the Southeast Quarter of Section 4,

Township 39 South, Range 1 East of the Willamette Base and Meridian, City of Ashland, Jackson County, Oregon.

PURPOSR:

To survey, monument and plat the ownership of the clients into two (2) parcels of land as set forth on the accompanying map and as reviewed and approved by

the City of Ashland Planning staff.

PROCEDURE:

This office conducted Minor Land Partition P-57-1990 in which these two parcels were then shown as Parcel No. 1. The existing house, which is situated on Parcel No. 2 of this survey, was partitioned from the remainder of the Richey property. The remainder of the survey is as shown on the accompanying map.

BASIS OF BEARING:

True Meridian at the North-South centerline of Section 4, as derived from the National Oceanic and Atmospheric Administration (formerly Coast and Geodetic Survey) survey net established in 1968 and filed in the office of the Jackson County Surveyor.

April 6, 1991

Swain Surveying, Inc. 27 1/2 North Main Street Ashland, Oregon 97520

ref: BR 1419T.NAR

Tax Lot 1400, 39-1E-04CA Tax Lot 402, 39-1E-04DB

PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 8, 1966
EVERETT L. SWAIN

REGISTERED

* * RECEIVED * *

Date 4-10-91 By 85

This survey Consists of:

______ sheet(s) Map

_____ page(s) Marrative

JACKSON COUNTY
SURVEYOR