

The Second Secon

SURVEY NO.

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

SURVEY FOR: Esther Giffen

2000 Ashland Mine Road Ashland, Oregon 97520

DATE: September, 1991

LOCATION: Southeast Quarter of Section 6, Township 39 South, Range 1 East, Willamette Meridian, Jackson County, Oregon.

PURPOSE: To survey and divide the tact as approved by the Jackson County Planning Department per File No. 91-1-MP.

PROCEDURE: I located the Section and Quarter corners as shown. The South Quarter corner was proportioned and set per Survey 9861, but after a long search I could not locate it, so I too proportioned it's position. The location of Ashland Mine Road was used as the centerline of the existing asphalt surface. I set boundary corners as shown on the attached map.

BASIS OF BEARINGS: The Basis of Bearings is North 89 52' 58" East along the east-west centerline of Section 6 per Survey no. 9681.

SURVEYED BY: James Andrews
837 E. Jackson
Medford, Oregon 97504

