

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

The position for the NE 1/16 corner as determined on Filed Survey 10877 was accepted. It appears like the Westerly 2 monuments set on File Survey No. 6432 were located from calculated positions to controlling corners and not from actual filed ties. These monuments were not accepted.

PROFESSIONAL LAND SURVEYOR

Sa D. Ca

OREGON JULY 16, 1967 GARY D. KAISER No. 803

GARY D. KAISER R.P.L.S. ORE. 803 C.W.R.E. ORE. 73

The second secon

KAISER SURVEYING

19440 HIGHWAY 62 EAGLE POINT, OREGON 97524 PHONE
SHADY COVE (503) 878-3995
MEDFORD PHONE/FAX (503) 779-8040

SURVEY NO. 12846

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

SURVEY FOR:

MICHAEL J. BEGLEY

1108 SAN TOMAS AQUINO ROAD CAMPBELL, CALIFORNIA 95008

SURVEY BY:

KAISER SURVEYING 19440 HIGHWAY 62

EAGLE POINT, OREGON 97524

LOCATION:

NE % of Section 31, T. 37 S., R. 2 W., W.M. Jackson

County, Oregon

BASIS OF BEARINGS:

Straight line between the center % corner and East % corner section 31 per filed Survey No. 1673 - N89°

56'W

DATE:

January 22, 1992

PURPOSE:

To monument that tract described in Inst. No. 90-03442 O.R.. Also to determine if the existing gravel roadway falls within that 60' wide roadway easement described in Inst.

No. 66-ØØ594 O.R.

PROCEDURE:

Initiated an EDM Traverse at the

East % corner to Section 31 and ran to the 1" axle monumenting the center % corner, then continued the traverse to close a loop around the subject premises. Ran an additional close loop traverse to tie the remaining monuments indicated as found.

Found existing monuments at the CE 1/16 corner, center % corner, CN 1/16 corner and at the NW corner of the subject premise which were determined to have been correctly set on their respective original surveys and within allowable accuracy limits. It was noted that the surveyor of filed Survey No. 7337 did not choose to accept the 1" axle at the center % corner or the BR. disk in concrete at the CE 1/16 corner.