## SURVEY FOR

JACKSON COUNTY PARKS & RECREATION DEPT. COUNTY COURT HOUSE MEDFORD, OREGON 97501

\* RECEIVED \*

Date 7-13-92 By 85

This survey Consists of:

sheet(s) Map

- parr(s) Narrative

JACKSON COUNTY SURVEYOR

N.W CORNER D.L.C. 4! FD PROJECTING 4" THE I" & IRON PIPE WITH 21/2" & BRASS CAP PER JACKSON COUNTY SURVEYOR'S OFFICE MAP OF SURVEY

ALONG THE SOUTH LINE OF D.L.C. 40 LOCATED IN

Note that the first of the control o

THE S.E. I/4 OF SECTION 5 AND THE SW. & S.E. I/4 OF SECTION 4 T. 38 S., R.IW., W.M.

PROJECT NO. 92-5

SURVEY BY

VERLYN THOMAS JACKSON COUNTY SURVEYOR COUNTY COURT HOUSE MEDFORD, OREGON 97501

FD. 8" DEEP AND O.O!" NORTH OF LINE, A 1" Ø IRON PIPE PER RECORDED SURVEY NO. 1287.

SET FLUSH

507.23

S 89°44'45" E 3962.29

944.00 ( \$89°44'45"E 3862.18" PER S/N 10946 )

PROJECTING I

S.E. CORNER D.L.C. 40 FD. PROJECTING 2" THE 1/2" 0 IRON PIPE WITH 3" 0 BRASS CAP PER JACKSON COUNTY SURVEYOR'S OFFICE

727.18

FD. FLUSH AND 0.02' SOUTH OF LINE, A 5/8" Ø PIN FER RECORDED SURVEY NO 10403

FD. 8" DEEP AND O.13' NORTH OF LINE, A I" Ø IRON PIPE PER "PEPPER 9 TAYLOR SUBD." OF 1923. PIPE REGISTERED BENT NORTHERLY PROFESSIONA

280.00

## EGEND

- FD. D.L.C. MONUMENTS AS NOTED

BASIS OF BEARINGS

SET 5/8"x 24" REBAR WITH 11/2" Ø ALUMINUM CAP AFFIXED TO THE TOP AND MARKED "JACKSON COUNTY C.S."

FD. MONUMENTS AS NOTED

SCALE: |" = 400"

DATE JUNE 1992

38 IW. 488 8 5 /

VERLYN D. THOMAS

May ONEGON

2. 1937

LANY

13062

## SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR: Department of Parks and Recreation

County Courthouse Medford, Oregon 97501

SURVEY BY:

Verlyn Thomas

Jackson County Surveyor

County Courthouse Medford, OR. 97501

DATE:

June, 1992

LOCATION:

Southeast Quarter of Section 5, and the Southwest and Southeast Quarters of Section 4, Township 38 South, Range 1 West, Willamette Meridian, Jackson County, Oregon.

PURPOSE:

To retrace south line of D.L.C. 40 along north line of Medford Mobile Estates, and determine extent of encroachments along said

PROCEDURE: Conducted a traverse between the reestablished Northwest corner of D.L.C. No. 41 to the reestablished Southeast corner of D.L.C. No. 40, with survey ties to monuments of record along said D.L.C. line.

Set 5/8"x24" iron pins with aluminum caps stamped "Jackson County C.S." on said D.L.C. line as shown on the accompanying map.

BASIS OF BEARING: Survey No. 10946 for the D.L.C. line as shown on the accompanying plat.

Job No. 92-5

REGISTERED PROFESSIONA

\* \* RECEIVED \* \*

Date 7-13-92 By BS

This survey Consists of:

sheet(s) Map

 $oldsymbol{L}$  paca(s) Narrative 1960 THOMAS JACKSON COUNTY

SURVEYOR