APPROVIL

Ashland Planning Commission

PA No. 92-035

We certify that pursuant to authority granted to us by the Ashland Planning Commission in open meeting APPLC, 14 1992 this map is hereby approved.

Dated this day of August, 1992.

President

Examined and approved this the 29 day of July, 1992.

City Surveyor.

PARTITION PLAT NO. P- 80-1992 LOCATED IN

N.E. 1/4 SEC. 15, T. 39 S., R. I E., W. M., JACKSON CO., OR.

MADGE CENTER, 1932 HIGHWAY 66 ASHLAND, OREGON 97520


RECORDING

Filed for record this the 13 day of 190, 1992 at 190 O'clock Am. and recorded as partition plat No. 190 No.

Index Volume 3, Page 80

County Surveyor File No. 13104

There are no water rights appurtent to this property.



Page 2

A concrete block wall has been constructed along the different lines with the exception of along the most extreme west line. The Wall was constructed by Jack Center (surveyors father) over a period of several years. The location was by mutual agreement of adjacent owners and the expense was shared. The location of the wall is noted on the attached partition plat.

Monumentation established during record survey No. 10168 along the east line were utilized as control along that line.

The southeast corner point for parcel 3 is situated in the south end of the concrete block wall. A 3 inch diameter iron fence corner post exists at the corner point location making establishment of a standard iron pin monument impossible. In addition a irrigation pipe exists adjacent to the iron post. The owner requested that no monument be established at the point. The corner point is referenced by a P-K nail (cemented) in the top of a concrete diversion box (S.W. corner). and an iron pin established by Surveyor E.L. Swain during R. S. 10168. Refer to Detail 'A' on the attached plat.

DATE OF SURVEY:

Commenced March 20, 1992, completed June 29, 1992.

SURVEYOR:

* * RECEIVED * * Date_8-13-92 By &

This survey Consists of:
________sheet(s) Map

1 pp ((s) flarrative

JACKSON COUNTY
SURVEYOR

HAROLD L. CENTER

Registered Professional Land Surveyor

Oregon Certificate No. 1071

2604 David Lane Medford, Or. 97504

REGISTERED
PROFESSIONAL
LAND SURVEYOR

O R E G O N
JULY 30, 1976
HAROLD L CENTER
No. 1071

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

Madge Center 1932 Highway 66 Ashland, Or. 97520

LOCATION:

NE 1/4 Section 15, Township 39 South, Range 1 East, Willamette Meridian, Jackson County,

Oregon.

BASIS OF BEARING:

Solar Observation

PURPOSE:

To partition the parcel of land described within Volume 420 Page 496 of the deed records of Jackson County, Oregon as shown on the attached

partition plat.

PROCEDURE:

I began this survey with the recovery of previously established monuments from record surveys No. 6055, 7245, 7955, and 10168. I also recovered the 1977 County Surveyor monument for the corner to Sections 10, 11, 14 and 15.

No centerline monumentation was recovered for control of the reconstructed Oregon State Highway No. 66 (reference R.S. 6055) for stations 23+98.19, POT 31+50 or 34+98.27. Monumentation was recovered along the southerly right-of-way line at Faith and Sherwood Streets and was utilized to control the north line of the parcel. During the reconstruction of Highway No. 66 in 1971-72 the portion of land situated between the existing right-of-way and the original deed line was taken by eminent domain action reference Jackson County Circuit Court Case No. J# 72-839-L. The intent of the court action was to take for public use all land situated north of the monumented line.

The north and south lines were held parallel to the north half of the east line of Section 15 and the east and west lines held parallel to the southerly right-of-way line of the highway.