


Quarter-section corner on the north boundary of Section 5. Found Jackson County Surveyor  $2\frac{1}{2}$  inch diameter brass cap, 12 inches deep, marked

Date: November 20, 1991



Roger R. Roberts LANDMARK SURVEYING 205 West Ninth Street Medford, Oregon 97501

T39S R1E 5BD TL 2300

and spirately seed and confidence of the season of the property of the seed of

## SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 205.250 OREGON REVISED STATUTES

SURVEY FOR:

Robert V. and Pauline M. Sullivan

525 Sheridan Street Ashland, Oregon

LOCATION:

Northwest quarter of Section 5 in Township 39 South, Range 1 East of the Willamette Meridian, Jackson

County, Oregon

**PURPOSE:** 

City Planning Department PA-034, Minor Partition. Locate and monument the exterior boundaries of the parent tract and partition into three parcels.

PROCEDURE:

The south boundary of the property, as described in Volume 517, Page 217 of the Deed Records of Jackson County, was found to be partially monumented by Filed Survey No. 6270. The most westerly portion of the south boundary was held at the deed record bearing of "West" to meet the west boundary.

The deed description does not call for the west boundary to be the north-south one-sixteenth line in the northwest quarter of Section 5. However, a review of the early deed descriptions of the neighboring properties indicated that the west boundary should coincide with the 1/16th line. Due to a lack of adequate survey control to determine the location of this line, a boundary line agreement was obtained between the client and the owners of the four properties adjoining the subject property along its west boundary. This agreement is now recorded as Instrument No. 92-07066 of the Official Records of Jackson County.

One-half inch diameter pipes were found along the north boundary, as shown on the plat. These monuments were believed to have been set by J.A. McCall during that survey reported in McCall Field Book C, page 44. A copy of this book is available in the Office of the County Surveyor. The location of these monuments were held to control the alignment of the north boundary.

## MONUMENT DESCRIPTIONS:

Southwest corner of Donation Land Claim No. 38. Found the Jackson County Surveyor 2½ inch diameter brass cap, 15" deep, marked T39S R1E

C.S. 1986

Station BILLINGS. Found brass cap in concrete, 4" deep in centerline of canal access road, marked SWAIN SURVEYING BILLINGS

1972 Survey Monument