

NW Cor. DLC #41
North 0.11

N. line DLC #41 per RS 6466.
(S89°48'10"E 633.64)
N89°47'40"W 633.18



(S46°17'00"E
N85°13'34"W
147.52)
147.54

RS 6466

M. 05 26.54N
564.38

(L=47.14
R=30.00)

(S3.47)
(S3.40)
S44°28'39"W
(S44°27'10"W)

L=135.14
R=170.00

(107.34)
107.41
S89°55'55"W
(WEST)

142.51 (142.52)
N45°32'50"W

RS 6466

MAP OF SURVEY

Located in the S.W. 1/4 of Sec. 4 and the
N.W. 1/4 of Sec .9, T.38 S., R.1 W., W.M.
Jackson County, Oregon

SURVEY FOR: La Clinica Del Valle
c/o Abeloe & Associates, A.I.A.
816 West 10th Street
Medford, OR 97501

SURVEY BY: L.J. Friar & Associates, P.C.
Consulting Land Surveyors
304 South Holly Street
Medford, Oregon 97501
Phone: (503) 772-2782

- LEGEND:
- ⊙ = Found County Surveyor's Brass capped monument & accessories.
 - = Found 5/8" iron pin per Survey No. 6466.
 - = Set 5/8" x 24" iron pin w/ plastic cap mkd. L.J. FRIAR & ASSOCIATES.
 - () = Record data per deed & Survey No. 6466.

BASIS OF BEARING: Survey No. 6466
DATE: February 9, 1993 SCALE: 1" = 30'

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

PURPOSE: To survey and monument the corners of the client's tract in conjunction with a topographic survey.

PROCEDURE: Made ties to existing monuments set by Survey No. 6466 and found them to be in good order, with the exception of the Southwest corner which was bent out of position and the pin on the Northerly line of the tract which has been destroyed. Using map record bearings re-established the destroyed corner. Made tie to N.W. corner of DLC No. 41. Those monuments found as well as those set are as shown hereon.

REGISTERED
PROFESSIONAL
LAND SURVEYOR
James E. Hibbs
OREGON
JULY 17, 1986
JAMES E. HIBBS
2234
Expires 12-31-93

** RECEIVED **
Date 2-16-93 By JF
This survey consists of:
1 sheet(s) Map
0 page(s) Narrative
JACKSON COUNTY
SURVEYOR

ASSESSOR'S MAP 381W04 TL600