

RICHARD G. TEMPLIN

PROFESSIONAL LAND SURVEYOR 2042 Sandra Pl. Medford, Oregon 97504 (503) 776-0991 • 474-7720

13399

NARRATIVE

Survey No.

SURVEY FOR: Boise Cascade Corp.

P.O. Box 100

Medford, Oregon 97501

Se 1/4 of Section 27, Township 33 South, Range 2 LOCATION:

West, of the Willamette Meridian, Jackson County,

Oregon.

PURPOSE:

To run and mark true line as shown on

accompanying plat.

DATE:

March 8, 1993

BASIS OF BEARING:

Bearings based upon B.L.M.

Administrative Survey, Jan. 1985.

PROCEDURE

Tied the South and East Quarter corners, along with the SE corner of Section 27, S 1/16 corner set on R.S 3290 and the B.L.M. C 1/4 position. Ties to the S 1/4 and the E 1/4 corners checked very close to the B.L.M. Administrative survey. I accepted the C 1/4 position, along with the S 1/16 corner set on R.S. 3290. Computed the SE 1/16 corner position and set:

* * RECEIVED * * Date 3-9-93 By B This survey Consists of: __ shoet(s) Map

_ page(s) Narrative

JACKSON COUNTY SURVEYOR

A 5/8"x 30" rebar with yellow plastic cap marked, "TEMPLIN LS 2359", from which I scribed the following bearing tree:

A Cedar, 10" diameter bears N 57°E, 13.1 feet, scribed " SE1/16S27" "BT".

A Cedar, 9" diameter bears N 570W, 10.6 feet, scribed "SE1/16S27" "BT".

I then computed the E 1/16 corner between Section 27 and 34 position and set:

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

RICHARD G. TEMPLIN

My Certificate Expires Dec. 31, 19 71

A 5/8"x 30" rebar with yellow plastic cap marked, "TEMPLIN LS 2359", from which I scribed the following bearing tree:
A White Oak, 10" diameter bears N 17°W, 20.1 feet, scribed "El/16S27" "BT".
A Douglas Fir, 12" diameter bears S 86°W, 50.9 feet, scribed "El/16S34" "BT".

I then ran true line between corners, as shown, blazed, painted, flagged and tagged said lines.