

## SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

LOCATION:

EAST HALF, SECTION 10 TOWNSHIP 35 SOUTH, RANGE 2 EAST, WILLAMETTE MERIDIAN, JACKSON COUNTY, OREGON. NORTH LINE MORTH BLUFF ADDITION AND EAST LINE EAST BLUFF

ADDITION, TOWN OF BUTTE FALLS.

SURVEY FOR:

MEDFORD CORPORATION

P.O. BOX 550

MEDFORD OREGON 97501

SURVEY BY:

ARTHUR R. RAMBO 735 VISTA PARK DRIVE EAGLE POINT OREGON 97524

DATE:

APRIL 15, 1993

BASIS OF BEARING: SURVEY NUMBER 4283 (CENTERLINE MAIN STREET)

PURPOSE:

TO MARK AND MONUMENT BOUNDARY BETWEEN MEDFORD CORPORATION PROPERTY AND PLATTED TOWN OF BUTTE FALLS AS SHOWN ON THE PLAT TO ACCOMPANY THIS NARRATIVE.

PROCEDURE:

A SEARCH OF RECORDS REVEALED PREVIOUS SURVEYS AND PLATS FOR THE TOWN OF BUTTE FALLS. UTILIZING THIS INFORMATION I MADE A SEARCH IN THE FIELD AND FOUND THE MONUMENTS FOR THE CENTERLINE OF MAIN STREET ON THE EAST BOUNDARY OF LAUREL AVENUE AND THE WEST END OF I MEASURED BETWEEN THESE MONUMENTS AND MAIN STREET. USED THIS DISTANCE TO PRORATE THE DISTANCES AGAINST THE OFFICIAL PLAT OF THE TOWN OF BUTTE FALLS. A SEARCH IN THE FIELD REVEALED THERE HAD BEEN CONSTRUCTION WORK FOR INSTALLATION OF SEWAGE LINES ALONG THE BOUNDARIES OF THE TOWN OF BUTTE FALLS AND THE NORTH AND EAST ADDITIONS OF THE TOWN OF BUTTE FALLS. I FOUND THAT THREE OF THE MONUMENTS SET ON SURVEY NUMBER 6591 WERE MISSING, I REPLACED THESE MONUMENTS ON THIS SURVEY. I ALSO FOUND THAT MONUMENTS SET SURVEY NUMBER 6590 HAD BEEN DISTURBED. I SET THE MONUMENTS NEEDED FOR THIS SURVEY AS SHOWN ON THE PLAT TO ACCOMPANY THIS NARRATIVE.

REGISTERED PROFESSIONAL AND SURVEYOR . Rando REGON ARTHUR R RAMAG No 1086

\* \* RECEIVED \* \* Date 4-16-93 By BF This survey Consists of: ! sheet(s) Map page(s) Narrative JACKSON COUNTY SURVEYOR