

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

SURVEY FOR: KOGAP Manufacturing Co.
P.O. Box 1608
Medford, OR 97501

LOCATION: The N.E. 1/4 of Section 2, T.36 S., R.2 E., W.M.,
Jackson County, Oregon.

PURPOSE: To mark new bearing trees due to the fact that
existing bearing trees will be cut by logging
operations

PROCEDURE: Utilizing the existing corner evidence, I mark two new
bearing trees to perpetuate the corner as follows.

At the angle point common to Section 2, T.36 S., R.2
E., and Section 36, T.35 S., R.2 E., W.M., found a 2
1/2" iron pipe with standard B.L.M. brass cap,
marked

AP
T35S R2E
S 36
S 2
T36S
1962

- from which original bearing trees:
 - A 24" Pine snag, now down, brs. S.78°E., 16.5'.
 - A 36" Pine brs. N.57°W., 21.8', scribe visible.
- and from which bearing trees mkd. by B.L.M. in 1962:
 - An 8" Fir snag brs. N.15°W., 54.4', scribe visible.
 - An 18" Fir brs. S.50°W., 31.7', healed blaze.
- and from which I scribe new bearing trees:
 - A 4" Fir brs. N.42°E., 17.2', mkd. XBT.
 - A 4" Fir brs. N.08°W., 11.1', mkd. XBT.

Measurements to found bearing trees taken to center of
tree at root crown. Measurements to new bearing trees
taken to center of blaze for bearing and to 16d nail
in side center of tree for distance.

BASIS OF BEARING: Official B.L.M. plat and field notes.

DATE: April 30, 1993

James E. Hibbs, PLS 2234
L.J. Friar & Associates, P.C.
Consulting Land Surveyors
304 South Holly Street
Medford, OR 97501
(503) 772-2782

Expires 12-31-93

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James E. Hibbs

OREGON
JULY 17, 1986
JAMES E. HIBBS
2234

** RECEIVED **

Date 5-6-93 By RF

This survey consists of:

0 sheets Map

1 page(s) Narrative

JACKSON COUNTY
SURVEYOR

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

SURVEY FOR: KOGAP Manufacturing Co.
P.O. Box 1608
Medford, OR 97501

LOCATION: The N.E. 1/4 of Section 2, T.36 S., R.2 E., W.M.,
Jackson County, Oregon.

PURPOSE: To mark new bearing trees due to the fact that
existing bearing trees will be cut by logging
operations

PROCEDURE: Utilizing the existing corner evidence, I mark two new
bearing trees to perpetuate the corner as follows.

At the angle point common to Section 2, T.36 S., R.2
E., and Section 36, T.35 S., R.2 E., W.M., found a 2
1/2" iron pipe with standard B.L.M. brass cap,
marked

AP
T35S R2E
S 36
S 2
T36S
1962

from which original bearing trees:
A 24" Pine snag, now down, brs. S.78°E., 16.5'.
A 36" Pine brs. N.57°W., 21.8', scribe visible.
and from which bearing trees mkd. by B.L.M. in 1962:
An 8" Fir snag brs. N.15°W., 54.4', scribe visible.
An 18" Fir brs. S.50°W., 31.7', healed blaze.
and from which I scribe new bearing trees:
A 4" Fir brs. N.42°E., 17.2', mkd. XBT.
A 4" Fir brs. N.08°W., 11.1', mkd. XBT.

Measurements to found bearing trees taken to center of
tree at root crown. Measurements to new bearing trees
taken to center of blaze for bearing and to 16d nail
in side center of tree for distance.

BASIS OF BEARING: Official B.L.M. plat and field notes.

DATE: April 30, 1993

James E. Hibbs, PLS 2234
L.J. Friar & Associates, P.C.
Consulting Land Surveyors
304 South Holly Street
Medford, OR 97501
(503) 772-2782

Expires 12-31-93

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James E. Hibbs

OREGON
JULY 17, 1986
JAMES E. HIBBS
2234

** RECEIVED **
Date 5-6-93 By BF
This survey Consists of:
0 sheet(s) Map
1 page(s) Narrative
JACKSON COUNTY
SURVEYOR