


ambiguous. The river has obviously moved Southwesterly since 1963 when Filed Survey No. 2323 was made and it is the opinion of the writer that the current Southwesterly property line is some distance Southwesterly from said monumented line as indicated on the accompanying map by the heavy dasher line. Survey No. 12207 indicated the same conclusion, the Southwesterly property line of Tax Lot 2500 has moved Southwesterly from the line shown on Filed Survey No. 2323.

Filed No. 2323 was use to write the descriptions utilized in Inst. Nos. 82-93142 of and 82-93143 O.R., consequently the found monuments set on said survey along the Northerly and Northwesterly boundaries of the subject tract were used to establish the Southerly boundary, which is a boundary created by said deeds. Bearings were rotated from the original calls by 9° 96' 46" counter-clockwise to agree with the difference found between record and measured on said Northerly and Northwesterly boundaries and record distance were held.

The true East boundary of the West-half of the NE % of Section 3 was held for the East boundary of subject tract with the lines as established on Survey Nos. 2323 and 1731 extended to intersect said line.



GARY D. KAISER R.P.L.S. ORE. 803 C.W.R.E. ORE. 73

KAISER SURVEYING

19440 HIGHWAY 62 EAGLE POINT, OREGON 97524

PHONE SHADY COVE (503) 878-3995 Fax (503) 878-3995

SURVEY NO.

14167

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

SURVEY FOR:

RETA STENOIEN

13014 SE 279TH PLACE

KENT, WA 98031

SURVEY BY:

KAISER SURVEYING

19440 HWY. 62

EAGLE POINT, OR 97524

LOCATION:

North-half of Section 3, T. 34 S., R. 1 W., W.M., Jackson County,

Oregon

BASIS OF BEARINGS:

Filed Survey No. 13675 (East bdry.

West-half NE % Section 3)

DATE:

August 17, 1994

PURPOSE:

To monument tract described in Inst. No. 82-Ø3142 O.R.. Also set line monuments near where existing roadways enter and exit the subject

property.

PROCEDURE:

Utilizing EDM Equipment, initiated

the survey at traverse points established on Filed Survey No. 13675 and traversed around the subject property.

The Northerly and Northwesterly boundaries were located per found monuments set on Filed Survey Nos. 2323 and 1731. The monument set on said Survey No. 2323 for the North-Northwesterly property corner has apparently been destroyed, it falls in the center of an existing roadway. This corner was reset at proportionate distance between found monuments as shown.

The most Westerly monument set on the Northwesterly property boundary on said Survey No. 2323 has been destroyed by highwater (as has been other river monuments set on said survey, none were found). Said Westerly monument was reset at record distance (100.00') from the witness corner found set on said survey.

The Southwesterly boundary (the river boundary) of the subject property is referred to as the "mean water line" on deeds of record. This could be referring to the mean water line between high water and the low water or the mean Page 1 of 2