

Survey No. _____

Paul Rynning
County Surveyor
Medford, Oregon

Township 36 South, Range 4 West, Section 26, W.M.

SUBJECT: Re-establish Section Corner 23, 24, 25 and 26.

Found a 2 in. iron pipe set by the County Engineer on road survey which was used for the actual corner.

Found B.T. 18 in. black oak, bears N.46°W., 70.1 ft. (varies from record)

Found B.T. 16 in. black oak S.27½°W., 65.2 ft. (varies from record)

Two new additional trees scribed 301 BT., from which

Laurel 8 in. diam., bears S.5½°E., 22.6 ft.

Laurel 8 in. diam., bears N.44½°E., 14.6 ft.

Var. 19°

