

SURVEY NARRATIVE TO COMPLY WITH CHAPTER 209 OREGON REVISED STATUTES

SURVEY FOR:

Mel Sherbourne

3237 Carriage Drive Medford, Oregon 97501

LOCATION:

John R. Crews Subdivision in the Southeast 1/4 of Section 13, Township 37 South, Range 2 West, Willamette Meridian, Jackson County, Oregon.

PURPOSE:

To survey and monument the corners of the client's property.

EQUIPMENT:

Lietz Set 4 Total Station

PROCEDURE:

Two original monuments were found from the John R. Crews Subdivision; the 2" iron pipe shown along the west line of D.L.C. No. 61, and the 1" iron pin at the northwesterly corner of Lot 11, Block 3. The 2" iron pipe was shown as disturbed on Filed Survey No. 13842 and its position relative to the aforementioned D.L.C. line would indicate that it was moved slightly during fence construction. Therefore, much of the boundary of the client's property was based upon the location of the 1" iron pin, the D.L.C. corners, found monuments from Filed Survey No. 7655, and record bearings and distances from Filed Survey No. 7655 and the plat of the John R. Crews Subdivision. Two monuments were found from Filed Survey No. 13842. Both appear to have been moved during fence construction and did not fit the other monuments found.

BASIS OF BEARING:


The west line of Donation Land Claim No. 61, as shown on Filed Survey

No. 7655 and Filed Survey No. 13842.

DATE:

January 31, 1996

MARQUESS & ASSOCIATES, INC. 1120 East Jackson Street P. O. Box 490 Medford, Oregon 97501





Stuart M. Osmus Oregon Professional Land Surveyor No. 2464