Besis of Boarings 337.01 ELL Corner DLC 042. 225.46 (225.23 R\$2713) Position of angle iron per RS2713. MAP OF SURVEY Located in the S.W. 1/4 of Section 19. T.37 S., R.1 W., W.M. City of Medford Jackson County, Oregon RS818 & 2713 Position of angle iron per RS2713. SURVEY FOR: SURVEY BY: Lithia Properties 360 East Jackson Street Medford, OR 97501 L.J. Frier & Assoc.. P.C. Consulting Land Surveyors 304 South Holly Street Modford. Orogon 97501 Phono: (541) 772-2782 RIVERSIDE LEGEND: - Found County Surveyor's bress capped monument & accessories. ● - Found I exle. See RS2713. et el. 0 - Set 5/8" x 24" iron pin with plastic cap mkd. L.J. FRIAR & ASSOC. TL 500 e - Set brass washer mkd. LS2234 in lead plug in concrete. RS = Recorded Survey #. () - Record data as shown. JCDR - Jackson County Deed Records. DR - Deed Record. ORJCO - Official Records of Jackson County. Oregon. RS 6892 BASIS OF BEARINGS: DLC line per Survey No. 6892 as shown. DATE: September 13. 1996 UNIT OF MEASUREMENT - Feet SCALE: 1 - 30 TL 600 S. line V.235. P.99. JCDR per RS 6892. Roteining N68'34'25"E SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250 PUMPOSE: To survey and monument the exterior lines of the client's property'. Tied to the ELL corner of DLC #42 and to monuments found by RS 6892. Reset corners destroyed by construction per RS14169 as shown. Held map record distance per RS2713 for the N.W. & N.E. corners of the subject. Held map record bearing per RS2713 on the Ely. line of the subject tracts from the S.E corner previously monumented by RS14169. Those monuments found as well as those set are as shown hereon. PROCEDURE: RS14169 PROFESSIONAL Jans 2 9xills JULY 17, 1986 Renewal Date 6-30-97 371W19CC TL'S 500 & 600