

## LEGEND

- SET 5/8"X 24" REBAR WITH YELLOW PLASTIC CAP MARKED "TEMPLIN LS 2359"
- FOUND 5/8" IRON ROD PER " STAGECOACH HILLS SUBDIVSION. UNIT 3 "
- FOUND 5/8" IRON ROD WITH MCMAHAN YELLOW PLASTIC CAP.PER FUTURE SUBDIVSION NOT RECORDED TO THIS DATE.
- CALCULATED POSITION
- RECORD BEARING/DISTANCE PER " STAGECOACH HILLS SUBDIVSION. UNIT 3 .

BEARINGS BASED UPON " STAGECOACH HILLS SUBDIVISION. UNIT 3". THE WEST LINE OF LOTS 6 & 7. AS SHOWN.

## SURVEY NARRATIVE

To reestablish the Northeast and the Northwest corners of Lot 7, Block 4, of Stagecoach Hills Subdivision, Unit 3 ".

Bearings based upon West line of Lots 6 & 7, said Stagecoach Hills Subdivision.

PROCEDURE: I tied original Subdivision monuments, as shown. The Northwest corner of Lot 7, a found 5/8" iron rod, lies in a powerline ditch. This position has been determined as disturbed. I proportioned the Northwest corner of Lot 7 and set on line between the Southwest corner of Let 7 and the Northwest corner of Let 6. I then held record bearing and distance to the Northeast corner of Let 7, from which original monuments along the East line of Lot 7, checked very close to record. It might be noted that the Westerly right of way line of Coachman and Consetoga Drive have been disturbed due to the large cut banks.

> I then made ties to a building that encreaches on the lot line between Lote 6 and 7, as shown.

\* \* KECEMED \* \* REGISTERED PROFESSIONAL Date 1-2-97 By BF LAND SURVEYOR This survey Consists of Me & hh \_\_\_\_ sheet(s) Map (RICHARD 6. TEMPLIN) \_\_ page(s) Narrative JACKSON COUNTY
SURVEYOR

ly Gestificate Rughres Dec.St. 1972

RICHARD TEMPLIN LAND SURVEYING 100 POGRMAN CREEK RD. 879-9002 / 474-7729 JACKSONVILLE, GREGON

MAP OF SURVEY LOCATED IN LOT 7, BLOCK 4, OF STAGECOACH HILLS SUBDIVISION, UNIT 3 IN THE SE 1/4 OF SECTION 32, T. 37S.,R.2W., W.M.,

JACKSON COUNTY, OREGON SURVEYED FOR MR. JAM PAGNINI 805 BERKLEY WAY DATE NOVEMBER 22, 1996 JACKSONVILLE, OR. 97530