

## SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250, OREGON REVISED STATUES

**SURVEY FOR:** 

Ivy R. Doherty

11427 Blackwell Road Central Point, OR 97502

SURVEY BY:

Timberline KKB Land Surveying

Kerry K. Bradshaw LS 2271

P.O. Box 3064

Central Point, OR 97502

(541) 664-7510

cell (541) 944-6692

**BEARINGS:** 

East line of section 15 as shown on Government Land Office Plat of

subject Township (NORTH)

**PURPOSE:** 

To locate and monument the easement as described in Instrument No.

87-16677 of the Official Records of Jackson County, Oregon.

## **PROCEDURE**

The east and west 1/4 corners as well as the southeast corner of Section 15 were tied with a control traverse using a Pentax III total station.

The west 1/4 corner location was established by Filed Survey No. 7032, setting a 5/8" iron pin and two bearing trees in 1978. This monument has been destroyed by fence building, and fire had mostly destroyed the northerly BT; thus the corner position was re-established from the remaining BT and what evidence remained of the northerly BT. The position *held* was the southwest corner of the fence corner post, where it entered the ground.

The north line of Volume 383, Page 169, which controls the subject easement location, was determined to be parallel with the east-west centerline of the section, as property and road descriptions in the area suggest this was the intent. This also tends to fit existing fences better than the deed call of "West".

Alignments of the easement were calculated and monuments were set as shown on the Map of Survey.

June 19, 1997

\*\* RECEIVED \*\*

Date 9-24-97 By &

This survey Consists of:

\_\_\_\_\_ sheet(s) Map
\_\_\_\_ page(s) Narrative

JACKSON COUNTY
SURVEYOR

\*\* REGISTERED
PROFESSIONAL
LAND SURVEYOR

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REGISTERED
PROFESSIONAL
LAND SURVEYOR

SREGON
JULY 16, 1987
KERRY K BRADSHAW
2271

Expires 12/31/97