

6111

1/4 COR.

FOUND
CEDAR 20° S 23° E 37.62'
MKD. 1/4 S
CEDAR 22° S 38° W 13.20'
HEALED

SET
1-1/2" X 36" IRON PIPE
IN MOUND OF STONE
MKD. R.S. 298

VARIATION
20° 42' E

SEC. COR.

FOUND
D. FIR 18" N 14° E 46.86'
HEALED & DEAD
B. OAK SNAG 28° S 44° E 40.26'
HEALED
B. OAK STUMP S 56° W 19.80'
DECAYED

NEW B.T.'S
D. FIR 16" N 43° 15' E 16.50'
D. FIR 14" S 66° E 6.60'
D. FIR 12" S 27° 30' W 29.04'
D. FIR 16" N 43° W 15.18'

SET
2" X 36" IRON PIPE
28" IN GROUND
MKD. R.S. 298

8 9
17 16

MAP

SHOWING

SECTION CORNER AND 1/4 CORNER
SECTION 8, T. 34 S., R. 4 W.W.M.
JACKSON COUNTY, OREGON

CORNERS LOCATED APRIL 15, 1957
FROM ORIGINAL WITNESS
TREES

SCALE: NONE

NO. WR657

