


N.W. COR. D.L.C. NO. 74,  
T.37S., R.2W., W.M.  
(FOUND)



NORTH 1158.42'  
EAST 20.00'  
SOUTH  
D.L.C. LINE SOUTH  
WIL ARNOLD LANE  
20.00'

D.L.C.  
NORTH 169.11'  
EAST 142.00'  
SOUTH 149.22'  
582° 01' 40" W 143.39'  
EXISTING WIRE FENCE

**BOUNDARY SURVEY OF PROPERTY**  
SITUATE IN  
D.L.C. No. 93, T.37S., R.2W., W.M.  
JACKSON COUNTY OREGON  
FOR  
EDWIN G. FARRELL  
L.P. LOVEJOY L.S. MEDFORD, ORE.  
SCALE: 1" = 50'  
RECORD BEARINGS USED  
° = SET 5/8" STEEL PIN

S.W. COR. D.L.C. NO. 75  
(FOUND)

N.W. COR. D.L.C. NO. 78  
(FOUND)

REGISTERED  
**OREGON**  
LAND SURVEYOR  
LELAND P. LOVEJOY  
NOVEMBER 18, 1949  
262

*Leland P. Lovejoy*

Survey Narrative to Comply with Section 87-330

1947 Oregon State Laws

Survey for: Edwin G. Fjarli  
4017 Jacksonville Highway  
Medford, Oregon

Purpose of Survey: To establish property corners.

Survey Location: D. L. C. No. 93, Township 37 South,  
Range 2 West, Willamette Meridian,  
Jackson County, Oregon.

Survey Procedure: Found D. L. C. corners and survey  
points and used as basis for survey  
control. Set 5/8" steel pins as  
shown on map.

Leland P. Lovejoy  
Registered Land Surveyor

Work completed August 15, 1961

