

P.O. Box 1625 Medford, OR 97501 541.772.6880-tel

541.772.9573-fax info@hea-inc.com

Survey Monument Replacement Record

Situated in Sections 17 and 20, T36S, R1W, WM

Jackson County, Oregon

April 7, 2003

Survey By: Richard L. Bath, PLS 1069

For: Urban Renewal Agency of Jackson County

10 South Oakdale, Room #214, Medford, Oregon, 97501.

Re: Filed Survey No. 17259, Horizontal Control for Highway 62 Storm Drain.

Due to construction activities which have disturbed or destroyed the locations of certain monuments shown on Filed Survey No. 17259, we have replaced those monuments with 5/8" x 24" rebar with orange plastic cap stamped "HARDEY ENG & ASSOC."

The monuments replace are numbered 375, 376, 378, and 1016 as shown on said filed survey.

These monuments have been replaced in their record recovery positions prior to construction activities and no analysis of the correctness of their location has been made.

Richard L. Bath, PLS 1069
Director of Surveying
Hardey Engineering & Assoc., Inc.
1600 Sky Park Drive, Suite E
Medford, OR 97504
Ph. 541-772-6880

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 30, 1976
RICHARD L. BATH
No. 1069

RENEWS 12/31/03

* RECEIVED *

Date_5-7-03_By_

This survey Consists of:

______ sheet(s) Map
_______ page(s) Narrative

JACKSON COUNTY
SURVEYOR