



MARK E. BOYDEN
R.P.L.S. ORE. 281
108 MISTLETOE ST., MEDFORD, OREGON 97501
PHONE (503) 773-6000

SURVEY NO. 18314

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

SURVEY FOR: Sharon & John Wall
1819 Colestine Road
Ashland, OR 97520

SURVEY BY: Boyden Surveyors
108 Mistletoe Street
Medford, OR 97501

LOCATION: NE ¼, Section 36, T. 40 S., R. 1 E., W.M.
Jackson County, Oregon

BASIS OF BEARINGS: County Filed Survey No. 10202



DATE: June 14, 2004

PURPOSE:

1. To monument the East boundary of the Wall property (Tax Lot 1602 401E - 36).
2. Locate the building improvements encroachment across said East boundary.

PROCEDURE: Utilizing a top-gun E.D.M., traversed said boundary between monuments found shown on Filed Recorded Survey No. 10202. Also located building improvement encroachments as shown hereon. Also made tie to the brass cap monument set for the Northeast corner of Section 36 by the B.L.M.

It should be noted, that Filed Survey No. 3992 utilized a point 0.66 feet Easterly from said B.L.M. monument as the commencing corner for this survey.



BOUNDARY SURVEY

FOR: SHARON & JOHN WALL
1819 COLESTINE ROAD
ASHLAND, OREGON 97520

LOCATED in the NE 1/4, Sec. 36,
T.40S., R.1E., W.M., Jackson County,
Oregon

DATE: May 14 - June 14, 2004

BY: Boyden Surveyors
108. Mistlétøe Street
Medford, Oregon 97501

LEGEND

- FOUND MONUMENT SET ON F.S. 3992
- SET 5/8" x 24" REBAR / AL. CAP "STAMPED" BOYDEN PLS 281
- ⊙ FOUND MONUMENT SET ON F.S. 10202

FS. = FILED (COUNTY) SURVEY

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Mark E. Boyden
OREGON
MARK E. BOYDEN
281

Expires: 12/31/05

•• RECEIVED ••
Date 6-21-04 By MB
This survey consists of
1 sheet(s) Map
1 page(s) Narrative
JACKSON COUNTY
SURVEYOR

Sharon & John Wall
TL1602 401E36

