

SURVEY FOR:

Luis Machado
1020 Butte Falls Road
Eagle Point, OR. 97524

LOCATION:

N.E. 1/4 of Section 21,
T.35S.,R.1W., W.M.,
Jackson County, Oregon

SURVEY BY:

Kaiser Surveying
19754 Highway 62
Eagle Point, OR. 97524

DATE:

January 18, 2006

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bary D. Kaiser

OREGON
JULY 15, 2003
BARY D. KAISER
No. 52923
EXP. 6-30-07

LEGEND

- ✕ = Found Monument as Indicated
- △ = Found 5/8" Rebar - S.N. 8378
- = Found 5/8" Rebar with Plastic Cap - S.N. 16500
- = Set 5/8" x 30" Rebar with Plastic Cap marked "B. KAISER RLS 52923"
- S.N. = Filed Survey Number County Surveyors Office
- W.C. = Witness Corner
- () = Record/S.N. 16500
- (()) = Record/S.N. 812
- ((())) = Record/S.N. 16117
- (((())) = Record/INST. No. 99-48905 O.R.
- *- = Fence

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

PURPOSE: Boundary Survey of Tract described in INST. No. 2004-075519 O.R.

PROCEDURE: The boundary of desired tract was located from information on filed survey Nos. 16500 and 8378, INST. Nos. 99-48905 O.R. and 2004-075519 O.R.

** RECEIVED **
Date *1-18-06* By *BD*

This survey consists of:
1 sheet(s) Map
2 page(s) Narrative

JACKSON COUNTY
SURVEYOR

