

Survey Monument Replacement Record

Situated in Sections 20 and 21, T36S, R1W, WM

Jackson County, Oregon

P.O. Box 1625
Medford, OR 97501
541.772.6880-tel
541.772.9573-fax
info@hea-inc.com

May 26, 2006

Survey by: Richard L. Bath, PLS 1069

For: Urban Renewal Agency of Jackson County
10 South Oakdale, Room #214, Medford, Oregon, 97501

Re: Filed Survey No. 18909, Horizontal Control for Wilson Way & East Dutton Road

Due to construction activities which have disturbed or destroyed the locations of certain found monuments shown on Filed Survey No. 18909, we have replaced those monuments as follows:

Monuments numbered **633, 634, 635, 636, 637, 858, 859, and 618** have been replaced with a 5/8" x 24" iron rebar with Orange Plastic Cap stamped "HEA & Assoc"

These monuments have been replaced in their record recovery positions prior to construction activities and no analysis of the correctness of their location has been made.

Richard L. Bath, PLS 1069
Director of Surveying
Hardey Engineering & Assoc., Inc.
PO Box 1625
Medford, OR 97501
Ph. 772-6880
Fax 772-9573

(File: 381-59-04-MonReplacement.nar.wpd)

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Richard L. Bath

OREGON
JULY 30, 1976
RICHARD L. BATH
No. 1069

RENEWS 12/31/07

