FOUND CORNER INFORMATION

- 1 N 1/16 CORNER SECTION 30 ONLY, BLM BRASS CAP, 1968.
- (2) SECTION CORNER SECTIONS 19, 20, 29 & 30, BLM BRASS CAP 1966.
- (3) 1/4 CORNER SECTIONS 30 & 31, BLM BRASS CAP 1966.
- (4) SECTION CORNER SECTIONS 29, 30, 31 & 32, BLM BRASS CAP 1966.
- (5) CLOSING CORNER SECTIONS 19 & 30, BLM BRASS CAP 1983.
- (6) 1/4 CORNER SECTION 25 ONLY, BLM BRASS CAP 1968.
- (7) W 1/4 CORNER SECTION 30 ONLY, BLM BRASS CAP 1968.
- 8
 1/4 CORNER SECTIONS 29 & 30, BLM BRASS CAP & IRON PIPE LAYING ON GROUND, HAVING BEEN DISTURBED FROM ORIGINAL DF BEARING TREE BLOWN DOWN. CALCULATED TRUE CORNER POSITION FROM REMAINING THREE BEARING TREES:

 DF 26" DBH BEARS N71°25"W, 28.3 FEET (RECORD N67°30"W, 28.4 FEET).

 IC 22" DBH BEARS N51°14"E, 12.9 FEET (RECORD N55°E, 13.2 FEET).

 WHITE FIR 17" DBH BEARS N52°01"W, 62.8 FEET (RECORD N50°W, 62.7 FEET).
- (9) N 1/4 CORNER SECTIONS 19 & 30, BLM BRASS CAP 1983.
- E 1/16 CORNER SECTIONS 19 & 30, BLM BRASS CAP 1983, ACTUAL LOCATION DOES NOT MATCH RECORD CALLS.
 SET NEW MONUMENT SEE CORNER REFERENCE 18.
- (11) N 1/16 CORNER SECTIONS 29 & 30, COMPUTED, BLM BRASS CAP 1983 BEARS S61°21'26"W, 2.7 FEET.

SET CORNER INFORMATION

- NW 1/16 CORNER SET 5/8" x 24" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "LS 2011". WHITE FIR 15.6" DBH BEARS N78°40'E, 13.5 FEET, SCRIBED "NW1/16 S30 BT". WHITE FIR 26.1" DBH BEARS S73°39'W, 55.5 FEET, SCRIBED "NW1/16 S30 BT".
- CW 1/16 CORNER SET 5/8" x 24" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "LS 2011". DF 11" DBH BEARS S12 "41"E, 42.5 FEET, SCRIBED "CW1/16 S30 BT". DF 15.6" DBH BEARS N40 "50"W, 18.4 FEET, SCRIBED "CW1/16 S30 BT".
- C 1/4 CORNER SET 5/8" x 24" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "LS 2011".
 DF 9.2" DBH BEARS S31°51'W, 20.2 FEET, SCRIBED "C1/4 S30 BT".
 DF 15.6" DBH BEARS N76°37'W, 30.3 FEET, SCRIBED "C1/4 S30 BT".
- CS 1/16 CORNER SET 5/8" x 24" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "LS 2011". WHITE FIR 19.7" DBH BEARS S42°58"W, 24.25 FEET, SCRIBED "CS1/16 S30 BT". WHITE FIR 13.8" DBH BEARS N52°25"W, 31.3 FEET, SCRIBED "CS1/16 S30 BT".
- S 1/16 CORNER SECTIONS 29 & 30 SET 5/8" x 24" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "LS 2011".
 WHITE FIR 9" DBH BEARS S46°21"W, 24.3 FEET, SCRIBED "S1/16 S30 BT".
 WHITE FIR 15.5" DBH BEARS S33°46'E, 20.6 FEET, SCRIBED "S1/16 S29 BT".
- NE 1/16 CORNER SET 5/8" x 24" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "LS 2011". CEDAR 6.5" DBH BEARS N46°26'W, 5.5 FEET, SCRIBED "NE1/16 S30 BT". CEDAR 7" DBH BEARS N45°57'E, 25.1 FEET, SCRIBED "NE1/16 S30 BT".
- EAST 1/16 CORNER SECTIONS 19 & 30 SET 5/8" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "LS 2011".

 BLM BRASS CAP BEARS S85°03'36"E, 88.61 FEET.

 DF 37" DBH BEARS S39°21'E, 34.9 FEET, SCRIBED "E1/16 S30 BT".

 WHITE OAK 9.5" DBH BEARS N27°09'W, 22.5 FEET, SCRIBED "E1/16 S19 BT".

PROFESSIONAL LAND SURVEYED JULY 16, 1982 LLOYD B. SMITH

MAP OF SURVEY

LOCATED IN
SECTION 30,
TOWNSHIP 40 SOUTH, RANGE 3 EAST,
WILLAMETTE MERIDIAN
JACKSON COUNTY, OREGON

REMAINING CORNERS AS NOTED.

SURVEY FOR; MERIWETHER SOUTHERN OREGON LAND & TIMBER SURVEY BY:
SMITH SURVEYING
LLOYD "BUTCH" SMITH
7050 HIGHWAY 140
EAGLE POINT, OREGON 97524
(541) 826-2509

LEGEND

- ▲ FOUND MONUMENTS AS NOTED.
- SET MONUMENTS.

LINE MARKED THIS SURVEY.

- [...] G.L.O. RECORD.
- 1968 B.L.M. DEPENDENT RESURVEY.
- (...) 1983 B.L.M. DEPENDENT RESURVEY

