

2098 ⁴⁵/₈₆

SURVEY MONUMENT REPLACEMENT RECORD


Situated in Section 19, T36S, R1W, W.M. and Section 24, T36S, R2W, W.M.

Jackson County, Oregon

December 8, 2011

Survey By: Otto Ribanszky, PLS 72476

For: Urban Renewal Agency of Jackson County
10 South Oakdale, Room #214, Medford, Oregon 97501



Re: Filed Survey No. 20654 Horizontal Control and Monument Recovery for Ave "C"

Due to construction activities which have disturbed and/or destroyed the locations of certain monuments shown on Filed Survey No. 20654, we have replaced said monuments with 5/8" x 24" rebar with orange plastic cap stamped "HARDEY ENG & ASSOC."

The monuments replaced are numbered **547, 550, 558, 559, 570, and 571** as shown on said filed survey.

Those destroyed monuments have been replaced in their record recovery positions as shown on Filed Survey No. 20654 and no analysis of the correctness of their location relative to a deed corner position has been made.

Otto Ribanszky, PLS 72476
Project Surveyor
Hardey Engineering & Associates, Inc.
2870 Nansen Drive
Medford, Oregon 97504
Ph. 541-772-6880

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 15, 2003
OTTO RIBANSZKY
72476

RENEWAL DATE: 12/31/12