Tax Lot No. 351W08 - 510

MAP OF SURVEY SURVEY FOR: **SURVEY BY:** C.W. 1/16 CORNER -FOUND 1" IRON PIPE Kaiser Surveying Clayton and Kristen Note EXPOSED 12" 19754 Highway 62 901 Rogue River Drive Eagle Point, ÓR. 97524 Eagle Point, OR. 97524 LOCATION: DATE: S.W. 1/4 of Section 8, September 26, 2012 T.35S., R.1W., W.M., Jackson County, Oregon SCALE: 1" = 100' 30'1 CAP GONE STA. P.O.T. 48+93.83 1.84' (((1.55'))). -- N41'40'E. 0.19' S10"37'00"E [BASIS OF BEARINGS/S.N. 3295] N79'23'00"E 662.23' (((662.41'))) CURVE DATA S10°11'47"E, 310.57' 6.09,00, 2894.79' 310.72 S9'37'42"E, 253.224 5'00'49" 2894.79' 253.305' 0.54,40, 2894.79' 46.033' S12'35'26"E, 46.032 (((308.58'))) S. N. 12606 INST. No. 90-25504 O.R. **LEGEND** WIRE FENCE RUNS 0.5' NORTHERLY OF PROPERTY LINE-2785.89[°] ((2786.00°)) \circ = Found 5/8" Rebar S.N. 11136 and 12606 M = Found 5/8" Iron Pin - S.N. 3295 Unless noted otherwise 3 \Box = Found 5/8" Rebar S.N. 9377 ROGUE-RIVER Δ = Found 5/8" Rebar County Surveyor Roll Map 28/4 (((2786.00'))) ● = Set 5/8" x 24" Rebar with Plastic Cap marked "B. KAISER RLS 52923" FENCE ON PROPERTY LINE S.N. = Filed Survey Number -DRIVE (((((2785.46')))) County Surveyors Office () = Record/Jackson Co. roll map 28/4 (()) = Record/S.N. 3295STA_P.I_42+53.57_ ((())) = Record/S.N. 11136 and 12606INST. No. 2012-022124 O.R. 8.38 AC.± ((((()))) = Record/S.N. 9377- = FenceSTA. P.C. 39+46.07 FOUND 5/8" REBAR EXPOSED 9" ORIGIN UNKNOWN N79'23'00"E 620.52' ((((620.53')))) 1.82'-30' EXPOSED 6" N13'17'W, 1.84' S. N. 9377 REGISTERED **PROFESSIONAL** SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250 LAND SURVEYOR Boundary Survey of the tract described in Instrument No. 2012-022124 O.R.. Bay D/Coin PROCEDURE: Equipment used to perform survey was a Nikon DTM 530 total station. Information OREGON JULY 15, 2003 BARY D. KAISER No. 52923 from Filed Survey No. 3295, 9377, 11136, 12606 and Roll Map No. 28/4 along with recorded deeds were used to determine property boundaries. The Westerly boundary of the subject property was located from found monuments shown on Filed Survey No. 3295. A EXP. 6-30-13 1" iron pipe set on said survey was found for the C.W. 1/16 corner of Section 8, which is the commencing point for the deed description of the subject property. The Northwesterly property corner was then set at the record distance Southerly from said found 1" iron pipe. BUCKINGHAM CIRCLE 8. The Easterly property boundary is the Westerly right—of—way line of Rogue River Drive. * RECEIVED * Monuments were found on said line which are shown on Jackson County Surveyor roll map Date 2-28-12 By No. 28/4. The Southerly property boundary was determined from deed records and found monuments set on Filed Survey No. 9377, which monument a line parallel with and 46.00 This survey consists of: feet Southerly of the Southerly property boundary as shown hereon. The pin found set for ____ sheet(s) Map the Northwest corner of Parcel No. 2 of said survey 9377 was found to be 1.84 feet off, which could have been moved or set erroneously, while the pin found set for the Northeast ____ page(s) Narrative corner of said Parcel No. 2 was found at the record location and held. JACKSON COUNTY Monuments were set at the corners as shown and stakes set on the Southerly property SURVEYOR boundary as requested by the property owner.