

BOUNDARY SURVEY OF PROPERTY
 SITUATE IN
 S. 1/2 OF S.W. 1/4 SEC. 24, T.39S, R.2W, W.M.
 JACKSON COUNTY OREGON
 FOR
 HARRY B. MARSHALL
 L.P. LOVEJOY L.S. MEDFORD, OREGON
 SCALE: 1"=200' AUGUST 6, 1963
 BEARINGS BY SOLAR OBSERVATION
 * SET 5/8" IRON PIN


SURVEY NARRATIVE TO COMPLY WITH SECTION 87-3301947 OREGON STATE LAWS

Survey For: Harry B. Marshall
246 East 10th Street
Medford, Oregon

Purpose of Survey: To subdivide the South Half of the Southwest Quarter of Section 24, Township 39 South, Range 2 West, Willamette Meridian, Jackson County, Oregon, into four parcels.

Survey Location: South Half of the Southwest Quarter of Section 24, Township 39 South, Range 2 West, Willamette Meridian, Jackson County, Oregon.

Survey Procedure: Found Quarter and Section Corners as shown on map and subdivided the Southwest Quarter in accordance with standard procedure. Established the South One-sixteenth Corner and set 5/8" iron pin, from which a 6" White Oak bears North $26-1/4^{\circ}$ West 36.5 feet, a 6" Black Oak bears South $26-3/4^{\circ}$ East 14.5 feet, a pile of rock bears South $84-1/2^{\circ}$ West 7.0 feet. Established the CS One-sixteenth Corner and set a 5/8" iron pin, from which a 14" Bull Pine bears South 14.9 feet, an 8" White Oak bears South $61-1/2^{\circ}$ West 30.2 feet. Set 5/8" iron pins as shown on map.



Leland P. Lovejoy
Registered Land Surveyor

Work Completed August 6, 1963



Leland P. Lovejoy

NOVEMBER 18 1949
LELAND P. LOVEJOY
262