



BOUNDARY SURVEY OF PROPERTY
 SITUATE IN
 SECTION 27, 28, 33 & 34, T.37 S., R. 2 W., W.M.
 JACKSON COUNTY OREGON
 FOR
 LLOYD E. HAMLIN
 L.P. LOVEJOY L.S. MEDFORD, OREGON
 SCALE: 1"=100' JUNE 14, 1963
 BEARINGS PER COUNTY RECORDS OF N/L
 D.L.C. NO. 78,
 ○ = SET 5/8" IRON PIN
 ● = FD. 5/8" IRON PIN
 —X— EXISTING FENCE

REGISTERED
OREGON
 LAND SURVEYOR
 Leland F. Lovejoy
 NOVEMBER 10, 1949
 LELAND F. LOVEJOY
 262

RECEIVED
 JACKSON
 AUG 13 1963
 COUNTY
 SURVEYOR

D.L.C. NO. 75
 T.37S, R. 2 W., W.M.

D.L.C. NO. 78
 T.37S, R. 2 W., W.M.

BELLINGER LANE

SURVEY NARRATIVE TO COMPLY WITH SECTION 87-3301947 OREGON STATE LAWS

Survey For: Lloyd E. Hamlin
Arnold Lane
Medford, Oregon

Purpose of Survey: To establish boundaries and corners
of property sold.

Survey Location: Sections 27, 28, 33 and 34, Township 37
South, Range 2 West, Willamette Meridian,
Jackson County, Oregon.

Survey Procedure: Found D. L. C. Corners and other survey
corners and monuments, as shown on map,
and used as basis for survey control.
Re-established the following D. L. C. Corners,
which had been destroyed recently from
Records, Ties, etc.:

- NW Corner D. L. C. No. 75
- Set 5/8" iron pin with round head;
- SW Corner D. L. C. No. 75
- Set 5/8" iron pin;
- NW Corner D. L. C. No. 78
- Set 5/8" iron pin.

Set 5/8" iron pins as shown on map.

Leland P. Lovejoy
Registered Land Surveyor

Work Completed June 14, 1963

