



PART 2  
 SURVEY IN SEC. 32 & 33 T.37 S., R.2 W., WM.  
 WILTON WHITE

SCALE 1" = 100'  
 • = 5/8" PIN  
 NOS. SEE MAP.

BY EDWARD MC GINTY  
 MEDFORD OREGON  
 FEB 1963



N 0° 04' 40" W 22 14.57'  
1608.25'



DLC 91


CL - R = 11,459.16'  
 D = 0° 30'  
 L = 567.22'  
 TS = 283.67'

CL - R = 818.51'  
 D = 7° 00'  
 L = 182.60'  
 TS = 91.87'

PART 2  
 SURVEY IN SEC. 32 & 33 T.37 S., R.2 W., WM.  
 FOR  
 WILTON WHITE  
 63 - 5 - 1

BY EDWARD MC GINTY  
 MEDFORD OREGON  
 FEB 1963


SCALE 1" = 100'  
 • = 5/8" PIN  
 NO'S SEE NAR.



REGISTERED  
 OREGON  
 LAND SURVEYOR  
*Edward A. McGinty*  
 JULY 10, 1953  
 EDWARD A. MCGINTY  
 301

(1) N 68° 58' E 470.83'  
 CC. COR. NW. DLC. 85

8489



S 89°43'10" E

292.0'

(9)

N 89°43'10" W 1857.31'

0.77'

30'

748.04'

560.78'

(16)

1143.77'

(15)

175.74'

(4)

N 0°06'30" E

(10)

SE COR DLC 37

567.74'

(11)

SW COR DLC 90

PART OF THIS SUP.

DLC 90

431.95'  
S 50°37'20" E

(12)

406.70'  
S 67°11' E


DLC 91

L = 565.74'

(13)

664.96'  
S 70°01'10" E

N 0°04'40" W 2214.57'  
1608.25'



Survey No.

2439

Survey Narrative to comply with O.R.S. 209-205:

Survey for: Wilton White  
Kirtland Rd., C.P.

Survey by: Edward A. McGinty, L.S.  
2/20/64

BASIS OF BEARING: Survey No. 1339.

PRECEDENCE OF SURVEY

1. Found a  $1\frac{1}{2}$  in. iron pipe as per County re-estab. records.
2. Set a  $5/8$  in. x 24 in. iron pin 6 in. deep where stone has been for many years, and has since been removed during construction of road, this stone had been along the westerly side of an old fence corner, found remains of old fence corner and set and iron pin on the westerly side. This stone was first found by me in Feb. of 1958 and the line running North to corner at No. 4 has been the line established approx. 40 years ago between adjacent property of Fleming and Hueners.
3. Found a  $5/8$  in. iron pin at P. T. curve from County road records.
4. Set a  $5/8$  in. iron pin on the projection of the South line of Cardwells Add. This falls on the South side of corner fence post which has been accepted between Fleming and Hueners as the corner for about 40 years.
5. Found stone 0.03 ft. south of line.
6. At the SW. corner fence post approx. 12 in. deep found a  $5/8$  in. iron pin. This fence corner has stood many years, always has been recognized by the old residents as being the SE. corner of Cardwells Add.
- 7 & 8. See survey for the City of Jacksonville. No. 1937
9. See Survey No. 1937.
- 10 & 11. Previous estab corner, now of record, see Survey No. 1783.
12. 1910 road P.I. see survey for B. Fleming. No. 1871/
- 13 & 14. For County road P.I. "spike" County road was determined and procedure and layout was discussed with the County Engr. dept. The boundaries of lots in Cardwells Add. were determined at approx. proportional distance. The original Sub-division has several errors. The center line of the right of way was determined from evidence of old rail bed, fence, deeds and plat.  
Fence line, except for County road, are shown when they vary from property lines by any amount which may affect any adjacent property adversely.  
All monuments set are  $5/8$  in. iron pins, 24 in. long with-in 2 inches more or less of surface except those previously stated, monuments on the north and center line of the street in Cardwells Add. averaging 6 to 8 inches more or less below the surface.

REGISTERED  
OREGON  
LAND SURVEYOR

*Edward A. McGinty*

JULY 10, 1953  
EDWARD A. MCGINTY  
301