


2839



SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250

OREGON REVISED STATUTES

Survey for:

H. Bud Plankenhorn
920 Wilson Read
Ashland, Oregon

Survey by :

Charles H. Hurst, L.S.
765 Sunrise Avenue
Medford, Oregon

Bearing :

Based on meridian of recorded survey no. 2024

Purpose :

To separate the tracts shown on the attached plat,
a portion of the boundaries of which to coincide
with the approximate physical centerline of the
Talent Irrigation District East Lateral.

Procedure :

A 5/8" iron pin was previously set during the course of recorded survey no. 2755 (identified on the plat therefore as a reference point). This pin was set on the basis of testimony from Mr. George Nichols, now deceased, who said this was at or very near the position of the quarter corner common to Sections 20 and 29. He recalled the witness tree to the West (Now gone) with "surveyors marks" thereon (Rec. E. 87° 160 links). He stated that said corner monument was a post and that said corner was "pretty close on line with a row of power poles to the East". Mr. Nichols, who owned adjacent property prior to 1920, and whose knowledge of the area extended back to 1910, indicated that he helped build a fence running North from the corner monument, no East-West fence line then being in existence. The position so indicated checks with the 324 feet tie East to the physical centerline of Wilson Read per Read Petition No. 205.

For the purpose of this survey, it was determined that the boundary of the public road running North be located. Accordingly, a search was made for the quarter corner common to Sections 17 and 20, in order to determine its relation to the 5/8" pin set as a tentative quarter corner.

A search disclosed the following:

1/4 corner common to Sections 17 and 20, T. 38 S., R 1 E. W.M. Found stone mound from which a 11.4" white oak bears N. 89° 48' 30" E. 174.24 feet (Rec. E. 174.24') bearing a healed over face, 80+ annual rings in heal over, rotten heart, no scribing found, axe marks distinctly visible. Also, a 14" oak stump shell bears N. 35° 39' E. 120.12 feet (Rec. E. 35° E. 120.12'). Stump was cut 12" above ground and 2 inches below cut found in reverse impression was old face with distinct axe cut notch, said notch having healed over to a depth of 2 inches.


I sight section corner to the West and find bearing to be S. 89° 29' 50" W. (Rec. S. 89° 30' W. 2638.68 feet) and determine by triangulation distance to be 2649.5 feet. I determine position to be true corner in light of evidence mentioned and set a 1 $\frac{1}{2}$ " x 30" iron pipe for monument from which I scribe a 6" white oak "1/4 S 17 483 BT" which bears N. 30° 59' 30" E. 35.5 feet and a 11.6" white oak "1/4 S 20 483 BT" which bears S. 2° 44' 40" W. 21.85 feet. A 1" pipe with a cross on cap (cap broken off and found adjacent to pipe) was found bearing N. 18° 45' 30" E. 35.70 feet. Present were Robert Malette and Robert Wagner.

Running South, I find 5/8" pin set for tentative 1/4 corner to Sections 20 and 29 to fall S. 0° 00' 15" W. 5511.82 feet.

Accordingly, I find said pin to be within reason and expectation in accordance with testimony and corroborative evidence and accept same for 1/4 corner in lieu of information or evidence to contrary.

On this basis, I proceed with survey as shown.

Survey completed May 10, 1965



REGISTERED
OREGON
LAND SURVEYOR

Charles H. Hurst
OCTOBER 30, 1965
CHARLES H. HURST
493