

OCT 12 1965

Survey Narrative To Comply With Paragraph 209.250

Oregon Revised Statutes

SURVEY FOR:

Melvin Hall

1176 Old Stage Road Medford, Oregon.

LOCATION:

Tract situated in the South One half (1/2) of Section 20 and North One half (1/2) of Section 21, also Donation Land Claim 39 and 40, Township 37 South, Range 2 West, Willamette Meridian, in Jackson County, Oregon.

PURPOSE:

To establish corners and describe the tract of land shown on the attached map.

The Ell Corner of Donation Land Claim No. 40 was PROCEDURE: located as shown, it was also necessary to establish a line for the Southerly line of the tract to correspond to the Northerly line of Survey No.1941, the stone shown as found at the point of beginning of description, Deed Record Volume 317 Page 392 was not accepted as it, appears to be several fragments of a granite stone but no markings could be found and all fragments are loose and have been moved. The two 4 inch by 6 inch stones accepted are permanent and appear to be in their original positions. A determined effort was made to locate Oregon State Highway Departments survey notes and control for the newly constructed portion of the Old Stage Road, the notes apparently are not available and according to testimony of Will Robertson, Oregon State Highway Department Surveyor, there were never any permanent references established. The Oregon State Highway Department ties for property right of way descriptions were considered inadequate for this survey, therefor the existing road asphalt mat was used for control. Bearings were adapted from Rec-REGISTERED OREGON

orded Survey No.1625.

September 18, 1965

The state of the s

NOVEMBER 7 1947 J. A. HOFFBÜHR

222

AND SURVEYOR

J. A. Hoffbuhr Registered Land Surveyor

and a particular process of the particular section of the particular process of the particular part