

Butte Falls, Oregon
November 12, 1965

County Surveyor
Jackson County Court House
Medford, Oregon

Dear Sir;

Please record the following information pertaining to the surveys of the U. S. Public Lands.

I, D. A. Smeltzer, on or about 11-65 remonumented the following corners.

T. 34S, R2E, Will. Merid.

$\frac{1}{4}$ corner, Sections 22 & 23.

Found; Stone, $\frac{1}{4}$ scribe.

SW BT Fir, broken off above scribes.

Probable SE BT Cedar, down, rotted.

Scribed new BTs RS 461 BT,

5" W. Fir N10°W 20.6'

10" D. Fir S88°E 69.1'

$\frac{3}{2}$ corner.
10/11

Found; stone at calls.

SE BT OK.

NW BT good, fell at face, stump remains.

Scribed RS 461 BT,

12" D. Fir N79°W 12.7'

6" W. Fir N30°E 8.0'

T. 33S, R2E, Will. Merid.

$\frac{1}{4}$ corner, Sections 33, 34.

Found; 1 $\frac{1}{2}$ "x4' pipe set 1962 by RS 461.

SE BT. OK.

Scribed RS 461 BT,

8" Maple N40°W 33.1'.

T. 34S, R2E, Will. Merid.


$\frac{1}{4}$ corner, Sections 3 & 10

Found; Stone, scribed.

SW BT OK.

Scribed RS 461 BT,

13" Hemlock N38°W 33.3'.



Duane A. Smeltzer

